

Basic Vehicle Condition Guide

Report ID: 26,806,837

Pass

1

~

/

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance Steering performance

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Operation

Head lights Tail lights Indicators

Spare

Coolant condition Performance

Radiator / Hoses (visual)

19 May 2025 Created:

Fail

N/A

1

mm

mm

mm

 mm

4

5

5

1

/

1

1


1

Yes

Make: Model: Ford Fiesta **Body Style:** Hatchback Year: 2017 Registration: KTH678 **Reg Expiry:** 07 Feb 2026 WoF Expiry: **Odometer:** 14 Feb 2026 63,538 Kms **Good No:** 26806837 VIN: MPB8XXMXJ8HM76898 **Next Service:** 14/2/25 or 80000km Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Stone chips in windscreen,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Vehicle drove well.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)	· ·	
Evidence of Cam Belt Replacement: No	Kms:	Reversing camera	·
Inspected by: Aaron Johnson		Date: 19 May 2025	
I have read and understood this condition guide.	Name:	Signature:	