

Basic Vehicle Condition Guide

Report ID: 26,809,070


3 Version:

27 May 2025 Created:

Make: Model: Toyota Isis **Body Style:** Wagon Year: 2010 Registration: MHD5 Reg Expiry: 21 Sep 2025 WoF Expiry: **Odometer:** 06 Jun 2026 142,376 Kms **Good No:** 26809070 VIN: 7AT0H658X19006320 Next Service: 146577 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

2wd/

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

| | _ |
|---------|----------|
| General | Comments |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Uriah Pepene 22 May 2025 Inspected by: Date:

Name:

| | Pass | Fail | N/A | | |
|--|--------------|------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | \(\times \) | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | • | | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | |
| Left front | 4 | .0 | mm | | |
| Right front | 4.0 | | mm | | |
| Left rear | 5.0 | | mm | | |
| Right rear | 5 | .0 | mm | | |
| Spare | | Yes | | | |
| Suspension | | ı | | | |
| Suspension performance | ~ | | | | |
| Steering performance | \(\sigma \) | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | 1 | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | 1 | ı | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | - | | | | |
| Dashboard warning lights | \(\times \) | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | \(\times \) | | | | |
| Window winder FR | • | | | | |
| Window winder RL | <i>'</i> | | | | |
| Window winder RR | | | | | |
| Rear view mirrors | / | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 2 | | | | |
| Central locking | • | | | | |
| Remote locking | ~ | | _ | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | | | |

Signature: