

Report ID: 26,809,559 2 Version: 20 May 2025 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A	
Year:	2022	Registration:	PFM527	Reg Expiry:	12 Oct 2025	Engine	1			
WoF Expiry:	14 Apr 2026	Odometer:	48,823 Kms	Good No:	26809559	Oil level	~			
VIN:	JMFXTGF8WLZ030677	Next Service:	60000	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~			
			D		SP	Performance	~			
Key:		-0		-01-	31	Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
D = dent R = rust	s dia			710	HIVS	Operation	~			
PT = paint defe		r I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~			
C = crack					SC	Clutch			~	
P = pin dent	sc de				2414	CV joints			~	
						Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
	scutts S		DS		Р	Performance	~			
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~			
						Tyres (lowest observed tread depth of tyres)				
Rear airvent centre console damaged, Left mirror cover scratch						Left front	4.5 mm			
						Right front	5.	.0	mm	
						Left rear	3.	.0	mm	
Conditions During Body Inspection: Dry					Right rear	3.5 mm				
					Spare	Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
FWD Suspension perf						Suspension performance	<			
						Steering performance	۲			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpets	Cood					Tail lights	~			
	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dashboa	rd Card					Wipers (front & rear)	~			
	rd Good					Window winder FL	~			
						Window winder FR	~			
<u>General Comments</u>					Window winder RL	~				
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
CD (basic test onl									~	
						Number of keys	2			
Road Conditions During Test Drive: Dry Central locking							~			
Engine Timing Mechanism: Timing Chain							~			
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected	Inspected by: Arunachalam Subramanian Date: 19 May 2025									

I have read and understood this condition guide.

Name:

Signature: