

Report ID: 26,810,294 3 Version: 21 May 2025 Created:

Make:	Honda	Model:	FIT	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2009	Registration:	LYB537	Reg Expiry:	08 Jul 2025	Engine			L
WoF Expiry:	04 Jun 2026	Odometer:	118,776 Kms	Good No:	26810294	Oil level	~		
VIN:	7AT08G2YX18257864	Next Service:	128,000 kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	V		
	SC				PT	Performance	~		
Key:		-0	S PT PT	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent	- HE			TIS		Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent	110				세비	CV joints	~		
* = decals	sc 916			-NL	ELLER T	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs PT P S PT PT						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments			,,		Tyres (lowest observed tread	-	of tyre	 (کد
Dent in left side lower sill						Left front	3	,	
						Right front		., .4	 mm
						Left rear			mm
Conditions During Dody Inspections						Right rear	3.9 mm 4.6 mm		
Conditions During Body Inspection: Wet						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension	Yes		
									1
						Suspension performance	~		
						Steering performance Shock absorbers	~		
							~		
						Air Conditioning / Heater			<u> </u>
Interior Comments						Operation			
						Electrical / Accessories			
Seats	Wear on d	rivers seat				Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Glue resid	ue on dashboard				Wipers (front & rear)	~		
					_	Window winder FL	~		<u> </u>
Gonoral	<u>Comments</u>					Window winder FR	~		<u> </u>
						Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		ļ
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Hoani Saunders Date: 19 May 2025									
Date: 17 may 2023									

I have read and understood this condition guide.

Name:

Signature: