

Report ID: 26,811,020 2 Version: 26 Jun 2025 Created:

Make:	BMW	Model:	1 Series	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2018	Registration:	LNC615	Reg Expiry:	30 Sep 2025	Engine			
WoF Expiry:	10 Jun 2026	Odometer:	38,348 Kms	Good No:	26811020	Oil level	~		
VIN:	WBA1R520205C7503(Next Service:	48,200kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	his can be arranged to	or an additional of	.narge.	Coolant condition	~		
	SC S		Р		S	Performance	~		
Key:		=		505		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	PT AR			20	HILS	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					P SC	Clutch			~
P = pin dent	HP				2416	CV joints	~		
*= decals						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
in significant	S S	C	Р	S		Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	2	.1	mm
						Right front	2	.8	mm
						Left rear	2	.1	mm
Conditions During Body Inspection: Dry						Right rear	2.6 mm		mm
						Spare	No		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	eater		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Cood					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd C					Wipers (front & rear)	~		
	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Jason Young Date: 27 May 2025									

I have read and understood this condition guide.

Name:

Signature: