

Odometer:

Next Service:

Utility **Reg Expiry:** 07 Dec 2025 Good No: 26812489

Engine

Oil level

Noise

Smoke & fumes

Coolant condition

Suspension performance

Steering performance

Performance

Service	History:	Yes
---------	----------	-----

Note: This report is not a warranty

17 Jun 2026

MPBUMFF50MX335768

WoF Expiry:

VIN:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends **Cooling System** a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

90,749 Kms

96000

	ш	Performance	~		
Key:		Radiator / Hoses (visual)	V		
S = scratch	15	Fransmission	II		L
D = dent	ЪË				_
R=rust S 90 HIVS		Operation	~		
PT = paint defect		Noise	~		
C = crack	1	Clutch			
P = pin dent	١Ē	CV joints	~		
*= decals SC MM P	11	Wheel bearings	~		┢
SC = stone chips	╢╏	Brakes	•		L
W = significant scuffs S PSC SC S		Performance	•		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram		Hand Brake	~		
	1	Fyres (lowest observed tread	d depth	of tyre	es)
Windscreen Stone Chips		Left front	3.	0	m
		Right front	3.	0	m
	J↾	Left rear	3.	0	m
Conditions During Body Inspection: Dry	٦٢	Right rear	3.	0	m
	╡┠	Spare		Yes	
Under Carriage & Under Bonnet Inspection Comments		Suspension	1		

		Shock absorbers	~	
		Air Conditioning / Heater	• • •	
-		Operation	~	
Interior Commen	ts	Electrical / Accessories		
Seats	Good	Head lights	~	
Camata		Tail lights	~	
Carpets	Good	Indicators	~	
Panels	Good	Dashboard warning lights	~	
		Wipers (front & rear)	v	
Dashboard	Good	Window winder FL	v	
		Window winder FR	v .	
General Commer	<u>its</u>	Window winder RL	~	
-Partial service history	/	Window winder RR	~	
		Rear view mirrors	v .	
		Radio (basic test only)	~	
		CD (basic test only)	v .	
		Number of keys	2	
Road Conditions I	During Test Drive: Dry	Central locking	~	
		Remote locking	~	
Engine Timing Mechanism: Timing Chain		Sat. Nav. (basic test only)	~	
Evidence of Cam	Belt Replacement: Not Applicable Kms:	Reversing camera	~	

Inspected by: Sione Mae

27 May 2025 Date:

Report ID: 26,812,489 3 Version: 10 Jun 2025 Created:

Pass

V

V

V

V

V V

~

V

Fail

N/A

V

mm

mm

mm

mm

I have read and understood this condition guide.

Name:

Signature: