

Basic Vehicle Condition Guide

Report ID: 26,813,364


Version:

22 May 2025 Created:

Make: Model: Honda CRV **Body Style:** SUV Year: 2007 Registration: MTY456 Reg Expiry: 13 Aug 2025 **WoF Expiry: Odometer: Good No:** 29 May 2025 200,500 Kms 26813364 VIN: JHLRE48707C210781 **Next Service:** Overdue Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Underbody oxidation

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>		
Seats	Poor	
Carpets	Poor	
Panels	Poor	
Dashboard	Average	

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement:

Not Applicable Kms:

Pass Fail Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings	N/A		
Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings			
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings			
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings			
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings			
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings			
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings			
Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings			
Transmission Operation Noise Clutch CV joints Wheel bearings			
Transmission Operation Noise Clutch CV joints Wheel bearings			
Operation Noise Clutch CV joints Wheel bearings	·		
Noise Clutch CV joints Wheel bearings	·		
Clutch CV joints Wheel bearings	V		
CV joints Wheel bearings	~		
Wheel bearings			
Punkas			
Brakes			
Performance 🗸			
Hand Brake	1		
Tyres (lowest observed tread depth of tyr	 res)		
Left front 3	mm		
Right front 3	mm		
Left rear 2	mm		
Right rear 2	mm		
Spare Yes			
Suspension			
Suspension performance 🗸			
Steering performance			
Shock absorbers			
Air Conditioning / Heater			
Operation 🗸			
Electrical / Accessories			
Head lights	T		
Indicators 🗸	-		
Dashboard warning lights 🗸	-		
Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR	-		
Window winder FL			
Window winder FR			
Window winder RL Window winder RR	+		
Poor view mirrors			
Rear view mirrors	+		
Radio (basic test only)			
CD (basic test only)			
Number of keys 2	1		
Central locking	+		
Remote locking			
Sat. Nav. (basic test only)	V		
Reversing camera	W		

I have read and understood this condition guide.

Kilipati Mae

Name:

Signature:

22 May 2025

Date: