

Report ID: 26,813,987 1 Version: 23 May 2025 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2019	Registration:	MCU905	Reg Expiry:	08 Aug 2025	Engine			
WoF Expiry:	08 May 2026	Odometer:	65,430 Kms	Good No:	26813987	Oil level	~		
VIN:	MR0KA3CD101228221	Next Service:	69869	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	P	-0	P PW	-161-	SP	Radiator / Hoses (visual)	~		
S = scratch						,	Transmission		
D = dent	sc 6/6			The	EID S	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint defe C = crack					R	Clutch	•		~
P = pin dent	Htc					CV joints	~		
* = decals	SP PK			AL.	ET P	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs R P SC SP SP D									
		Noto: con	ne defects & blemishes			Hand Brake	く く		
Body Insp	pection Comments	note. son	le délects & blemisnes	illay not be disp	nayeu in the diagram		•	- <b>f t</b> wa	
Right C pillar pin dented and rust						Tyres (lowest observed tread depth of tyres)			
Left C pillar pin dented						Left front	7		mm
						Right front	8		mm
						Left rear	7		mm
Conditions During Body Inspection: Dry						Right rear 8 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & onder boi	metinspectic	<u>n comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonte						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Partial service history						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Tir	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		-
	-						*		
Inspected by: Sione Mae Date: 23 May 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....