

Report ID: 26,814,777 2 Version: 27 May 2025 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Wagon		Pass	Fail	N/A
Year:	2006	Registration:	HUS386	Reg Expiry:	09 Jun 2025	Engine			
	25 Feb 2026	Odometer:	203,459 Kms	Good No:	26814777	Oil level		~	
VIN:	7AT0C139X14504205	Next Service:		Service Histor		Smoke & fumes	~	V	
· · · · ·	74100159714504205		210009		y. NO	Performance	v v		
	port is not a warranty								
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Noise 🖌			
						Cooling System			
						Coolant condition	~		
Key:	S R SC		S D R SC S D R S		S D	Performance	~		<u> </u>
S = scratch						Radiator / Hoses (visual)	~		
D = dent	sscw Ale				AL SDPTW	Transmission			1
R = rust	SSC MIC			$1 \land$	SHUK	Operation	~		
PT = paint defe	ect N				S R SC	Noise	~		<u> </u>
C = crack						Clutch			~
P = pin dent * = decals	SRPSC DE					CV joints		~	
* = decals SRPT SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
	S R SC	n	S D R SC S D R S		S D R SC	Performance	~		
Body Insp	ection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Aircon & Headunit Removed Headlights Faded & Minor Stone Chips Windscreen						Left front	3.5 mm		
ricualignes						Right front	4	.0	mm
						Left rear	3.0 m		mm
Conditions During Body Inspection: Dry						Right rear	3.5 mm		mm
						Spare	No		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil & Right Inner CV Boot Seepage, Underbody Surface Rust - Expected for Age & Milege						Suspension performance	~		
	Bushes Cracked & Peris	,	ace hust - Expected to	TAge & Millege		Steering performance		r	
						Shock absorbers	V		
						Air Conditioning / Heater	I		1
						Operation		~	
Interior Comments						Electrical / Accessories			1
Seats	Average					Head lights	~		
	, weitige					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	A					Dashboard warning lights	-	~	<u> </u>
ranels	Average					Wipers (front & rear)	~	-	
Dashboa	rd Average					Window winder FL	~		
						Window winder FE	-		
General (Comments					Window winder FR Window winder RL	v		
							v		
Aftermarket Suspension No Jack, Tools or Spare Wheel						Window winder RR	~		<u> </u>
Interior Odour						Rear view mirrors	~		<u> </u>
Intermitten	t Engine Light - On Dur	ing Inspection				Radio (basic test only)			~
						CD (basic test only)			~
						Number of keys	1		1
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		<u> </u>
Engine Ti	ning Machanism	Timetime	Chain			Remote locking			~
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected	d by: Darren Beban					Date: 21 May 20	25		
Inspected	a by. Building beball					Date. 21 May 20			

I have read and understood this condition guide.

Name:

Signature: