

Basic Vehicle Condition Guide

Report ID: 26,820,805


2 Version:

31 May 2025 Created:

Make: Model: Hyundai Veloster **Body Style:** Hatchback Year: 2014 Registration: HJN885 Reg Expiry: 09 Apr 2026 **WoF Expiry: Odometer:** 15 Apr 2026 39,796 Kms **Good No:** 26820805 VIN: KMHTC61EMEU201032 **Next Service:** 50000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Greg Morgan 23 May 2025 Inspected by:

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
	1	
~		
~		
		~
~		
~		
~		
~		
l depth	of tyre	es)
2	.0	mm
3	.0	mm
3.0		mm
4	.0	mm
	Yes	
	ı	ı
~		
~		
/		
	ı	
/		
	I	
<i>'</i>		
<i>\</i>		
<i>\</i>		
•		
•		
•		
•		
•		
_		-
•		
•		
2		~
./		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	V

Signature: