

Report ID: 26,822,180 2 Version: 31 May 2025 Created:

Make:	Mazda	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	MHE432	Reg Expiry:	09 Feb 2026	Engine			
WoF Expiry:	11 Jun 2026	Odometer:	137,700 Kms	Good No:	26822180	Oil level	~		
VIN:	7AT0C12HX19141032	Next Service:	148,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	SD S		SD SD	W	S	Performance	~		
Key:	130 []3	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	S SC			210	S SC	Operation	~		
PT = paint defe	ect NP				11111	Noise	~		
C = crack						Clutch	~		
P = pin dent	S D SC				2416	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significan	W		S S			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments					Tyres (lowest observed tread depth of tyres)				
					Left front	t 6.3 mr			
					Right front	6.8 mm		mm	
						Left rear	6.	.2	mm
Conditions During Body Inspection: Dry					Right rear	6.2 mm		mm	
					Spare	Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	Conditioning / Heater		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	seats stain	ed otherwise go	od			Head lights	<		
Carpote						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Kyle Kelly Date: 25 May 2025									

I have read and understood this condition guide.

Name:

Signature: