

Basic Vehicle Condition Guide

Report ID: 26,823,353


7 Version:

12 Jun 2025 Created:

Make: Model: Holden Colorado **Body Style:** Utility Year: 2016 Registration: **KBN751** Reg Expiry: 26 Jan 2025 **Odometer:** WoF Expiry: **Good No:** 30 May 2026 101,609 Kms 26823353 MMU148EK0GH653401 VIN: Next Service: 111,609 Kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor crack in LH taillight.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good, missing floor mats.		
Panels	Good		
Dashboard	Good, steering wheel worn.		

General Comments

Inspected by:

One of the key remote worn.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Troy Smith

Evidence of Cam Belt Replacement: Kms: No

> 25 May 2025 Date:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	V		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	\(\times \)		
Radiator / Hoses (visual)	~		
Transmission	ı		ı
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	V		
Hand Brake	•		
Tyres (lowest observed tread	denth	of tyre	25)
Left front	I	.0	mm
Right front			mm
Left rear	8.0		mm
Right rear	3.5 6.5		mm
	0	.s Yes	111111
Spare Suspension		163	
Suspension performance			
Steering performance	-		
Shock absorbers	•		
	•		
Air Conditioning / Heater			
Operation	•		
Electrical / Accessories			I
Head lights	<i>V</i>		
Tail lights	~		
Indicators			
	· ·		1
Dashboard warning lights	<i>v</i>		
Dashboard warning lights Wipers (front & rear)	<i>v v</i>		
Dashboard warning lights	\(\times \)		
Dashboard warning lights Wipers (front & rear)	\(\times \) \(\t		
Dashboard warning lights Wipers (front & rear) Window winder FL			
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR			
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL	V V V V V V V		
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR	v v		
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors	v v		
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only)	v v		<i>V</i>
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	\(\times \)		<i>v</i>
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	\(\times \)		· ·
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	\(\times \)		v
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking Remote locking	\(\times \)		v

I have read and understood this condition guide.

Name:

Signature: