

Basic Vehicle Condition Guide

Report ID: 26,824,106


Version: 1

Created: 29 May 2025

Make: Model: Hyundai Elantra **Body Style:** Sedan Year: 2008 Registration: NNA861 **Reg Expiry:** 08 Nov 2025 WoF Expiry: **Odometer:** 22 Aug 2025 142,759 Kms **Good No:** 26824106 VIN: KMHDU41DR7U127485 Next Service: 152000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Bodywork is rough. Numerous scratches, cracks in the front bumper, paint fading on roof, paint scrapes front left corner of bumper, left rear corner of rear bumper and the bumper itself and on the right rear door. Dent on the left front door, left front A pillar, near the right rear door and bonnet

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leaks found. Looks to be coming from rocker cover.

Front right outer cv boot leaking grease.

Play in steering rack.

Interior Comments

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Inspected by:

Front left window does not go down with the drivers master switch.

Both sunvisors are broken. They have the light that comes on when you slide open to get the mirror.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Bryce Steele

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	~				
Performance	\(\triangle \)				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	~				
Radiator / Hoses (visual)	V				
Transmission					
Operation	~				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread depth of tyres)					
Left front	4 n		mm		
Right front	4		mm		
Left rear	6		mm		
Right rear	5		mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance		~			
Shock absorbers	~				
Air Conditioning / Heater					
Operation 🗸					
Electrical / Accessories					
Head lights	~				
Tail lights	~				
Indicators	\(\triangle \)				
Dashboard warning lights	~				
Wipers (front & rear)	~				
Window winder FL		~			
Window winder FR	~				
Window winder RL	~				
Window winder RR	V				
Rear view mirrors	~				
Radio (basic test only)	ンン				
CD (basic test only)	/				
Number of keys	1				
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)			~		
Reversing camera			~		

I have read and understood this condition guide.

Name:

Signature:

29 May 2025