

Report ID: 26,825,646 2 Version: Created: 30 May 2025

Make:	Honda	Model:	Odyssey	Body Style:	Wagon		Pass	Fail	N/A
Year:	2004		JPB97	Reg Expiry:	07 Jul 2025	Engine	I	I	1
WoF Expiry:	26 Jul 2025	Odometer:	159,687 Kms	Good No:	26825646	Oil level	~		
VIN:	7AT08G61X15086533	Next Service:	18/3/26 or 169000km	Service Histor	y: No	Smoke & fumes	~		
						Performance	r		
	port is not a warranty a guide only. Consid	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
diagnostic te	sting undertaken. The	vehicle has beer	n driven up to 50km/ł	h from cold. The	Vendor recommends	Cooling System	1		1
a full mechan	nical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	S SC W		S P S		S	Performance	r		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent	TE				Tan	Transmission			1
B = rust	PTW			710	HIL PT W	Operation	~		
PT = paint def	ect NP				10111	Noise	~		
C = crack						Clutch			~
P = pin dent	sc de				24114	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scuffs S W S S D S W S						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			es)
Hole in left rear bumper. Left front fog light lens cracked.						Left front	Left front 4 m		
Leit Hont IC	ng light lens clacked.					Right front	4	4	mm
						Left rear	5	5	mm
Conditio	ns During Body Ins	pection:	Dry			Right rear	5	5	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension	•		
Surface cor	rosion underneath vehi	cle.				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Average					Tail lights	~		
carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	ird Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Constant						Window winder FR	~		<u> </u>
<u>General Comments</u>						Window winder RL	~		<u> </u>
Vehicle drove well.						Window winder RR	~		<u> </u>
infotainme	nt screen working inter	mittently.				Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	1		T
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		<u> </u>
Engine Ti	ming Mechanism	Timing	Chain			Remote locking	~		<b> </b>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
LVIGENCE		ement. p	lot Applicable	11115.		Reversing camera	~		
Inspecte	d by: Aaron Johnson					Date: 30 May 20	25		
	,								
I have read	and understood th	is condition c	uide. Name:			Signature:			