

Report ID: 26,828,703 3 Version: 10 Jul 2025 Created:

Signature:

Make:	Honda	Model:	Inspire	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	Registration:	LJS386	Reg Expiry:	15 Oct 2025	Engine	1		L
WoF Expiry:	24 Jan 2026	Odometer:	173,664 Kms	Good No:	26828703	Oil level	~		
VIN:	7AT08G0TX17001775	Next Service:	26/11/25 or 181000km	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for any and mileage	Parts have not	been dismantled or	Noise	r		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	S W		S S		S	Performance	r		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust				715	HIVS	Operation	~		
PT = paint defe				$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack				+	РТ	Clutch			~
P = pin dent	110				ᅰЦ	CV joints	~		
* = decals	PT QIE			-No-	PTC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			L
W = significant	t scuffs S W		S SP		S	Performance	~		
Podulner	action Commonts	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			L 2S)
Roof, bonnet and hood has paint fade and clear coat peeling.						Left front 6 mm			
						Right front	6		mm
						Left rear	6		mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	roof liner s	agging wear and	tear on nanels			Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		<u> </u>
	1					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		<u> </u>
Vehicle dro	ve well.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		<u> </u>
Engine Tir	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 1(0,460	Reversing camera	~		
Inspected	Inspected by: Jayden Roxburgh Date: 10 Jul 2025								

I have read and understood this condition guide.

Name: