

Report ID: 26,833,108 Version: 1 Created: 03 Jun 2025

Make:	Nissan	Model:	Latio	Body Style:	Sedan		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>	MFP685	Reg Expiry:	26 Jan 2026	Engine	•		
WoF Expiry:	29 Apr 2026	Odometer:	127,662 Kms	Good No:	26833108	Oil level	~		
VIN:	7AT0DH90X19011124	Next Service:	136,000kms	Service Histor	<b>y:</b> No	Smoke & fumes	V		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional of	charge.	Coolant condition	~		1
	S S		SD SPW	S	S D	Performance	~		1
Key:	13 (13			5(0)-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			1
D = dent R = rust	S D SC	1		710	HIL SW	Operation	~		1
PT = paint def	ect NP	IT I			171A	Noise	~		1
C = crack					S D	Clutch			V
P = pin dent	HIS				74114	CV joints	V		1
*= decals SC 919 SW						Wheel bearings	~		
SC = stone chips						Brakes			1
W = significant scuffs S S S S S						Performance 🗸			1
De du lu ana attion Commente Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	depth	oftvre	L es)
Scratches in left rear taillight lens.						Left front			mm
						Right front	-	.0	mm
						Left rear		.2	mm
Conditions During Rody Inspections						Right rear		.2	mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
					Suspension performance	~		1	
, J	unts are very soft & wor n both rear tyres.	n, engine has mo	ovement in it when cha	anging into gear.	Rubber is	Steering performance	~		
pensining o	in both real tyres.					Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		1
Interior Comments						Electrical / Accessories	•		
Seats	Good					Head lights	~		
Jeats	Good					Tail lights	~		
Carpets	Average					Indicators	~		
Danala						Dashboard warning lights	~		+
Panels	Good					Wipers (front & rear)	~		+
Dashboa	rd Good					Window winder FL	~		+
						Window winder FE	~		
General Comments					Window winder RL	~			
Movement in engine mounts when changing into gear. Boot floor panel is bent out of shape. Carpet worn in right front foot well area.						Window winder RR	~		
						Rear view mirrors	~		
<u> </u>						Radio (basic test only)			
						CD (basic test only)	~		
									~
						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		<u> </u>
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			<b>v</b>
						Reversing camera			~
Inspected by: Jason Young Date: 30 M							25		
·									
I have read	and understood th	is condition c	uide. Name:			Signature:			