

Report ID: 26,834,494 1 Version: 04 Jun 2025 Created:

| Make:  | Holden  | Model:               | Captiva 7              | Body Style:        | SUV                  |  | Pass             | Fail | N/A      |  |
|--|---|----------------------|------------------------|--------------------|----------------------|--|------------------|------|----------|--|
| Year:  | 2013  | <b>Registration:</b> | GSR223                 | <b>Reg Expiry:</b> | 01 Jul 2025          | Engine                                       | I                |      |          |  |
| WoF Expiry:  | 18 Jun 2026                                     | Odometer:            | 196,172 Kms            | Good No:           | 26834494             | Oil level                                    | ~                |      |          |  |
| VIN:   | KL3CD266JCB089288                               | Next Service:        | 206155 Kms             | Service Histor     | <b>y:</b> No         | Smoke & fumes                                | ~                |      |          |  |
|  |   |                      |                        |                    |                      | Performance                                  | ~                |      |          |  |
|  | port is not a warranty<br>a quide only. Conside | eration is made      | for age and mileage    | . Parts have not   | been dismantled or   | Noise  | ~                |      |          |  |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |   |                      |                        |                    |                      | Cooling System                               |                  |      |          |  |
| a full mechan  | lical inspection prior to                       | purchase and ti      | lis can be arranged ic |                    | narge.               | Coolant condition                            | ~                |      |          |  |
|  | S   |                      | P                      |                    | Р                    | Performance                                  | ~                |      |          |  |
| <b>Key:</b><br>S = scratch   |   | =(0)                 |                        | 5(0)-              |                      | Radiator / Hoses (visu                       | ual) 🖌           |      |          |  |
|  |   |                      |                        |                    |                      | Transmission                                 |                  |      |          |  |
| R = rust   | SC PR   |                      |                        | 10                 | HI S                 | Operation                                    | ~                |      |          |  |
| PT = paint def   | ect NP  |                      |                        |                    |                      | Noise  | ~                |      |          |  |
| C = crack  |   |                      |                        |                    |                      | Clutch                                       |                  |      | ~        |  |
| P = pin dent   | sc de   |                      |                        |                    | 74II <u>L</u>        | CV joints                                    | ~                |      |          |  |
| * = decals   |   | 10                   |                        | 70                 | SP SP                | Wheel bearings                               | ~                |      |          |  |
| SC = stone chips<br>W = significant scuffs   |   |                      |                        |                    |                      | Brakes                                       |                  |      |          |  |
|  | S S   |                      | S D P                  |                    | Р                    | Performance                                  | ~                |      |          |  |
| Body Inst  | pection Comments                                | Note: son            | ne defects & blemishes | s may not be disp  | layed in the diagram | Hand Brake                                   | ~                |      |          |  |
|  |   |                      |                        |                    |                      | Tyres (lowest observed tread depth of tyres) |                  |      |          |  |
|  |   |                      |                        |                    |                      | Left front                                   | 3                | .2   | mm       |  |
|  |   |                      |                        |                    |                      | Right front                                  | 3                | .1   | mm       |  |
|  |   |                      |                        |                    |                      | Left rear                                    | 3                | .8   | mm       |  |
| Conditions During Body Inspection: Wet   |   |                      |                        |                    |                      | Right rear                                   | ight rear 5.6 mm |      |          |  |
|  |   |                      |                        |                    |                      | Spare Yes                                    |                  |      |          |  |
| Under Carriage & Under Bonnet Inspection Comments  |   |                      |                        |                    |                      | Suspension                                   |                  |      |          |  |
|  |   |                      |                        |                    |                      | Suspension performa                          | ance 🖌           |      |          |  |
|  |   |                      |                        |                    |                      | Steering performanc                          | e 🖌              |      |          |  |
|  |   |                      |                        |                    |                      | Shock absorbers                              | ~                |      |          |  |
|  |   |                      |                        |                    |                      | Air Conditioning / He                        | ater             |      |          |  |
|  |   |                      |                        |                    |                      | Operation                                    | ~                |      |          |  |
| Interior Comments  |   |                      |                        |                    |                      | Electrical / Accessories                     |                  |      |          |  |
| Seats  | Good  |                      |                        |                    |                      | Head lights                                  | ~                |      |          |  |
| Carpets  | Good  |                      |                        |                    |                      | Tail lights                                  | ~                |      |          |  |
|  | Good  |                      |                        |                    |                      | Indicators                                   | ~                |      |          |  |
| Panels   | Good  |                      |                        |                    |                      | Dashboard warning                            | lights 🖌         |      |          |  |
| Dashboa  | rd Average                                      |                      |                        |                    |                      | Wipers (front & rear)                        | ~                |      |          |  |
|  | rd Average                                      |                      |                        |                    |                      | Window winder FL                             | ~                |      |          |  |
| Concerté   |   |                      |                        |                    |                      | Window winder FR                             | ~                |      | <u> </u> |  |
| General  | <u>Comments</u>                                 |                      |                        |                    |                      | Window winder RL                             | ~                |      | <u> </u> |  |
|  |   |                      |                        |                    |                      | Window winder RR                             | ~                |      |          |  |
|  |   |                      |                        |                    |                      | Rear view mirrors                            | ~                |      | <b></b>  |  |
|  |   |                      |                        |                    |                      | Radio (basic test only                       |                  |      | <u> </u> |  |
|  |   |                      |                        |                    |                      | CD (basic test only)                         | ~                |      |          |  |
|  |   |                      |                        |                    |                      | Number of keys                               | 2                | 1    |          |  |
| Road Conditions During Test Drive: Dry   |   |                      |                        |                    |                      | Central locking                              | ~                |      |          |  |
| Engine T:  | ming Machanian                                  | T:                   | Chain                  |                    |                      | Remote locking                               | ~                |      |          |  |
| Engine Timing Mechanism: Timing Chain  |   |                      |                        |                    |                      | Sat. Nav. (basic test o                      | only) 🖌          |      |          |  |
| Evidence   | of Cam Belt Replac                              | ement: N             | lot Applicable         | Kms:               |                      | Reversing camera                             | ~                |      |          |  |
| Inspecte   | Inspected by: Flynn Burdon Date: 04 Jun 2025    |                      |                        |                    |                      |  |                  |      |          |  |
|  |   |                      |                        |                    |                      |  |                  |      |          |  |

I have read and understood this condition guide.

Name: .....

Signature: .....