

Report ID: 26,837,551 2 Version: 13 Jun 2025 Created:

Make:	Mazda	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2013	<b>Registration:</b>	QJH105	Reg Expiry:	17 Feb 2026	Engine			L	
WoF Expiry:	25 Jun 2026	Odometer:	136,106 Kms	Good No:	26837551	Oil level	~			
VIN:	7AT0C12HX23153896	Next Service:	146000	Service Histor	<b>y:</b> No	Smoke & fumes	~		<u> </u>	
						Performance	~		<u> </u>	
	port is not a warranty	aration is made	for and milaan	Darte have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechani	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~			
					Р	Performance	~			
Key:		-0	SC	-01-		Radiator / Hoses (visual)	~		<u> </u>	
S = scratch						Transmission				
D = dent	s sc			ZIN	HIL S	Operation	~			
R = rust PT = paint defe				$\prod $		Noise	~			
C = crack				$+ \mathbb{N}$		Clutch	•		~	
P = pin dent					세비	CV joints	~			
* = decals	sc 916			- NL	EIIP I	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs D PT P S P						Performance	~			
		Note: som	ne defects & blemishes	s may not be disc	layed in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	of tyre	 (کد	
L/F Door Mirror outer cover cracked ,						Left front				
						Right front	8.	-	mm mm	
						Left rear	5.		mm	
			_			Right rear			-	
Conditions During Body Inspection: Dry						Spare	6.0 mm No			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~		<u> </u>	
						Steering performance	~			
						Shock absorbers	-			
							~			
						Air Conditioning / Heater			<u> </u>	
Interior Comments						Operation				
						Electrical / Accessories Head lights				
Seats	Good						~			
Carpets	Average					Tail lights	~			
						Indicators	~			
Panels	Good					Dashboard warning lights	~		<u> </u>	
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>	
						Window winder FL	~		<u> </u>	
General	omments					Window winder FR	~			
						Window winder RL	~		<u> </u>	
·						Window winder RR	•		<u> </u>	
						Rear view mirrors	~			
						Radio (basic test only)	~		<u> </u>	
						CD (basic test only)	<b>/</b>			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>	
Engine Timing Mechanism: Timing Chain						Remote locking	~		<b> </b>	
						Sat. Nav. (basic test only)			~	
		ement. N	lot Applicable	11115.		Reversing camera			~	
Inspected	Inspected by: Chris Buckley Date: 30 May 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....