

Report ID: 26,839,452 4 Version: 06 Jun 2025 Created:

Make:	Honda	Model:	FIT	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2016	Registration:	PAK927	<b>Reg Expiry:</b>	20 Oct 2025	Engine			
WoF Expiry:	15 Jan 2026	Odometer:	110,425 Kms	Good No:	26839452	Oil level	~		
VIN:	7AT08G2YX21222320	Next Service:	120,438 Kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	charge.	Coolant condition	~		
	SC		[c]	S		Performance	~		
Key:		-0	<u>s</u>	- (M-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	SC DI			715	HIL SC	Operation	~		
PT = paint defe		F		$\left[ \left( \right) \right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc dR				7414	CV joints	~		
* = decals				Tool .	ELD SC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv – significan	S		S			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front	6.0 mm		mm
						Right front	6.5 mr		mm
						Left rear	4.	5	mm
Conditions During Body Inspection: Dry						Right rear	4.5 mm		mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock a							~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashhar						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
L						Number of keys	1		
Road Conditions During Test Drive: Dry							~		
	ning Machaniara	T:'.	Che e ine			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Caleb Spicer Lee Date: 03 Jun 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....