

Report ID: 26,846,461 1 Version: 09 Jun 2025 Created:

Signature:

Make:	Mercedes-Benz	Model:	Vito	Body Style:	People Mover		Pass	Fail	N/A
Year:	2012	Registration:	GLE935	Reg Expiry:	16 Nov 2025	Engine			
WoF Expiry:	10 Mar 2026	Odometer:	215,164 Kms	Good No:	26846461	Oil level	~		
VIN:	WDF63960323685355	Next Service:	unknown	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Consid		for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	his can be arranged fo	or an additional o	narge.	Coolant condition	~		
			S SC S SC		S * SC	Performance	~		
Key:				500-		Radiator / Hoses (visual)	V		
S = scratch D = dent						Transmission			1
D = dent R = rust						Operation	~		
PT = paint defe					70111	Noise	~		
C = crack						Clutch	~		
P = pin dent	*sc dle				74116	CV joints			~
"= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scuris SC S SC S * SC						Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			es)
						Left front	3.5 mm		mm
						Right front	4	.5	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Wet						Right rear	4.5 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leaks from gear box and engine						Suspension performance	~		
						Steering performance	~		
		Shock absorbers	~						
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	rear seats	fitted on wood				Head lights	~		
Comoto						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Average					Dashboard warning lights	~		
D!!						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	Central locking	~							
	-		Wet			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Dean Sinclair Date: 09 Jun 2025									
Inspected by. Date: 03 Juli 2023									

I have read and understood this condition guide.

Name: