

Basic Vehicle Condition Guide

Report ID: 26,848,140


Version: 2

Created: 10 Jun 2025

Make: Model: Hyundai 130 **Body Style:** Hatchback Year: 2014 Registration: HNA806 Reg Expiry: 28 Sep 2025 **Odometer:** WoF Expiry: 26 Sep 2025 150,958 Kms **Good No:** 26848140 VIN: KMHD251EMEU190090 Next Service: 155,000 Kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak and seepage

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Right rear parcel tray clip broken
Ticking noise in engine - suspect lifter noise

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Hoani Saunders Date: 09 Jun 2025

Name:

| | Pass | Fail | N/A | |
|---|----------------------------|------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | v v | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | V | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 1 | .9 | mm | |
| Right front | 4.6 | | mm | |
| Left rear | 4.0 | | mm | |
| Right rear | 4.9 | | mm | |
| Spare | | Yes | | |
| Suspension | | ı | | |
| Suspension performance | ~ | | | |
| Steering performance | <i>V</i> | | | |
| Shock absorbers | ' | | | |
| Air Conditioning / Heater | | 1 | 1 | |
| Operation | • | | | |
| Electrical / Accessories | | | | |
| Head lights | • | | | |
| Tail lights | • | | | |
| Indicators | - | | | |
| Dashboard warning lights | • | | | |
| Wipers (front & rear) Window winder FL | | | | |
| Window winder FL Window winder FR | • | | | |
| Window winder FR Window winder RL | V V V V V V | | | |
| Window winder RE Window winder RR | ., | | | |
| Rear view mirrors | • | | | |
| | | | | |
| Radio (basic test only) CD (basic test only) | V | | | |
| Number of keys | 2 | | | |
| Central locking | • | | | |
| Remote locking | <i>y</i> | | | |
| Sat. Nav. (basic test only) | | | V | |
| Reversing camera | | | ~ | |
| g camera | | | | |

Signature: