

Report ID: 26,848,425 3 Version: 22 Jun 2025 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2014	Registration:	JND467	Reg Expiry:	09 Jun 2025	Engine		1	4
WoF Expiry:	25 Jun 2026	Odometer:	106,710 Kms	Good No:	26848425	Oil level	~		
VIN:	MNTVCUD40A0601923	Next Service:	117000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		1
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		1
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and the	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S D		S P S		SP	Performance	~		
Key:	30	-0		-01-	sr	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	S D SC W	1		715	SDC	Operation	~		
PT = paint def		FI		$\left(\left \right\rangle \right)$		Noise	~		
C = crack					S	Clutch	~		
P = pin dent	LANG HIS				게	CV joints			~
* = decals	S PT SC 91			-No-	AD SP	Wheel bearings	~		
SC = stone chips						Brakes	-		
W = significant scuffs S R S D P W S D P W S						Performance	~		1
Dodula		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		+
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
Left Canopy Door Latch Misaligned						Left front	6.0 mm		-
Left Steps Dented Right Taillight Cracked - Condensation						Right front	-	.0	mm
night rainig		laon				Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear		.5	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		1
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		1
Interior Comments						Electrical / Accessories	•		
Seats Drivers seat torn					Head lights	~			
						Tail lights	~		+
Carpets	Average					Indicators	~		+
Panels	Average					Dashboard warning lights	~		+
	Average					Wipers (front & rear)	~		+
Dashboa	rd Average					Window winder FL	~		+
						Window winder FR	~		+
General Comments						Window winder RL	~		+
re-registered						Window winder RR	~		+
						Rear view mirrors	~		+
						Radio (basic test only)	~		+
						CD (basic test only)	~		+
						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking	· ·		
Road Conditions During Test Drive: Dry						Remote locking	~		+
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	+		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	•								
Inspecte	d by: Samuel Weir					Date: 06 Jun 20	25		

I have read and understood this condition guide.

Name:

Signature: