

Basic Vehicle Condition Guide

Report ID: 26,852,397


Version: 7

Created: 23 Jul 2025

Make: Model: Toyota Landcruiser Prado **Body Style:** Wagon Year: 1996 Registration: BGL390 **Reg Expiry:** 01 Nov 2023 WoF Expiry: **Odometer:** 21 Aug 2025 423,451 Kms **Good No:** 26852397 VIN: 7A8H62L0703034294 Next Service: 0 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Left tail light damaged

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Four wheel drive

Oil leak

Transmission leak

Surface rust

		_			
Inte	erior	ິ (ດ	mm	เคท	ts

Seats	Drivers seat torn, Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

General Comments

Timing belt light is on

Due for a service

Front left park light bulb needs replacing / Loose interior panels, Gear stick loose, rear right window does not operate

possible issue with front right shock

Injector issue -smoking and not hurning oil

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 416,000

Inspected by: Jaykib Collins Date: 08 Jun 2025

I have read and understood this condition guide.

Name:

Signature:

Sat. Nav. (basic test only)

Reversing camera