

Report ID: 26,858,000 Version: 1 12 Jun 2025 Created:

Make:	Honda	Model:	Jazz	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2003	Registration:	BED529	Reg Expiry:	21 Jul 2025	Engine	1	1	
WoF Expiry:	18 Mar 2026	Odometer:	271,168 Kms	Good No:	26858000	Oil level	~		
VIN:	JHMGD18503S213316	Next Service:	overdue	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	p ort is not a warranty a guide only. Consid		for age and mileage	Parts have not	been dismantled or	Noise	~		
diagnostic te	sting undertaken. The	vehicle has been	n driven up to 50km/ł	n from cold. The	Vendor recommends	Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch	AT .			NG G	Tan	Transmission			1
D = dent R = rust	S SC W	1		715	S SC W	Operation	~		
PT = paint defe		FI		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent	Lange Hills				74114	CV joints	~		-
* = decals	S D SC 91			-No-	FID SSC	Wheel bearings	~		
SC = stone chips						Brakes	-		
W = significant scuffs						Performance	~		
Dealerteen		Note: son	ne defects & blemishe	s may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	oftvre	L es)
Stone chip with cracks above reg tags and bullseye in front of interior mirror. Water in spare wheel well. Wet									mm
and dirty at	inspection time					Right front		.0	mm
						Left rear		.0	mm
Condition	as During Pody Inc	noction	Mat			Right rear		.0	mm
Conditions During Body Inspection: Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		1
Requires fro	ont brakes					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
		Operation V							
Interior Comments						Electrical / Accessories	•		
Seats Average						Head lights	~		
	Avelage					Tail lights	~		
Carpets	hole drive	er footwell				Indicators	~		+
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		+
Dashboa	rd Average					Window winder FL	~		+
						Window winder FR	~		
General Comments						Window winder RL	~		+
Air conditioning and heating systems good temperature at inspection time						Window winder RR	~		+
			attare at inspection till			Rear view mirrors	~		+
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	3		<u> </u>
Road Conditions During Test Drive: Wet						Central locking	·		
Road Conditions During Test Drive: Wet						Remote locking	~		+
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	•								
Inspected	d by: Gary Adams					Date: 11 Jun 20	25		

I have read and understood this condition guide.

Name: