

Report ID: 26,863,142 2 Version: 03 Jul 2025 Created:

| Make: | Holden | Model: | Trax | Body Style: | SUV | | Pass | Fail | N/A |
|--|--------------------------|----------------------|------------------------|--------------------|----------------------|--|--------|------|-----|
| Year: | 2019 | Registration: | MAZ357 | Reg Expiry: | 24 Sep 2025 | Engine | 1 | | I |
| WoF Expiry: | 09 May 2026 | Odometer: | 71,397 Kms | Good No: | 26863142 | Oil level | ~ | | |
| VIN: | KL3BA7689KB841201 | Next Service: | 13/3/26 | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | his can be arranged fo | or an additional o | charge. | Coolant condition | ~ | | |
| | | | SC SC | | | Performance | ~ | | |
| Key: | | -0 | | 500- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| R = rust SSC A S | | | | | | Operation | ~ | | |
| PT = paint defect | | | | | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | s sc dl | | | | 2416 | CV joints | ~ | | |
| | | | | | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| W = Significan | | | S SC | | S | Performance | ~ | | |
| Body Inst | pection Comments | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| Good | | | | | | Left front | 6. | .0 | mm |
| | | | | | | Right front | 6.0 mr | | mm |
| | | | | | | Left rear | 5. | .0 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 5.0 mm | | |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| Carpets | Good | | | | | Tail lights | ~ | | |
| | Good | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Good | | | | | Wipers (front & rear) | ~ | | |
| | | | | | | Window winder FL | ~ | | |
| Concert | | | | | | Window winder FR | ~ | | |
| <u>General Comments</u> | | | | | | Window winder RL | ~ | | |
| Fwd | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 2 | | |
| Road Con | ditions During Tes | t Drive: | Wet | | | Central locking | ~ | | |
| | ming Mechanism | Timina | - Thain | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Lvidence | | | lot Applicable | 11115. | | Reversing camera | ~ | | |
| Inspected by: Harry Clark Date: 12 Jun 2025 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: