

Basic Condition Guide

Report ID:	26,956,245	Version:	4
Created:	19 Nov 2025		

	Diffe	—		Created: 1	
Make:	Audi	Model:	Q3		
Body Style:	Wagon	Year:	2015	Engine	
Rego No.:	PFM410	Rego Expiry:	04 May 2026	Oil level	
WoF Expiry:	10 Jun 2026	Odometer:	127,638 Kms	Smoke & fum	
Good No.:	26956245	VIN:	WAUZZZ8U7ER138076	Engine perfor	
Next Service:	137625 kms	Service History:	No	Noise	
Note: This report is	not a warranty	`		Coolant cond	
diagnostic testing ur	ndertaken. The vehicle has b	een driven up to 50km/h	arts have not been dismantled or n from cold. The Vendor recommends a	Cooling perfo	
full mechanical insp	ection prior to purchase an	d this can be arranged fo	or an additional charge.	Radiator / Ho	
Key				Transmission	
	= Rust $C = CT =$ Paint defect $P = P$		3	Operation	
D = Delit F			ie Chips	Noise	
S		s s	S	Clutch	
	\sim $(0)_{\epsilon}$		SPT	CV joints	
		<u> </u>		Wheel bearin	
M				Brakes	
1		11 —		Performance	
	Hand brake				
	Tyres (lowest				
		+	S	Left front	
				Right front	
	\prec			Left rear	
S		D W		Right rear	
Note: some defects	and blemishes may not be	displayed in the diagra	m	Spare	
Body Inspecti	on Comments			Suspension	
				Suspension p	
				Steering perfe	
				Shock absorb	
Conditions Du	ring Body Inspection		Dry	Air Condition	
Under Carriag	je and Under Bonnet	Inspection Comm	ents	Operation	
				Electrical / A	
				Head lights	
				Tail lights	
Interior Comn	nents			Indicators	
Seats:	Seats: Average				
Carpets:	Good			Wipers (front	
Panels:	Average			Window wind	
Dashboard:	Good			Window wind	
General Comr				Window wind	
222.4. 401111				Window wind	
				Rear view mir	
				Radio (basic t	
Road Condition	ns During Test Drive	Dry		CD (basic test	
nous contaition	is builing itst blive	, , y		כט וטמטוכ נכטנ	

		Requires	
	OK	Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	✓ ✓		
Noise	/		
Coolant condition	•		
Cooling performance	•		
Radiator / Hoses (visual)	'		
Transmission			
Operation	1		
Noise	1		
Clutch			/
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	1		
Hand brake	~		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			5 mm
Right front			5 mm
Left rear			4 mm
Right rear			4 mm
Spare	N/A		
Suspension			
Suspension performance	1		
Steering performance	1		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	1	Ι	
Electrical / Accessories		l	
Head lights	/		
Tail lights	· ·		
Indicators	·	-	
Dashboard warning lights	1		
Wipers (front & rear)	·	-	
Window winder FL	V		
Window winder FR Window winder FR	~	-	
Window winder FR Window winder RL	1		
	1	-	
Window winder RR		-	
Rear view mirrors	V		
Radio (basic test only)			
CD (basic test only)	2	<u> </u>	
Number of keys	2	ı	1
Central locking	/		
Remote locking	'		
C. L /	1		/
Sat. nav. (basic test only) Reversing camera	1	-	

I have read and understood this condition guide:

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 19 Nov 2025

Eleoit Kumar

Eleoit Kumar

NAME

Timing Chain

No

Yes

SIGNATURE

Kms