


Basic Condition Guide

Report ID:	26,980,706	Version:	4
Created:	16 Nov 2025		

Make:	Hyundai	Model:	Kona
Body Style:	SUV	Year:	2019
Rego No.:	MHP545	Rego Expiry:	20 Dec 2025
WoF Expiry:	25 Aug 2026	Odometer:	99,893 Kms
Good No.:	26980706	VIN:	KMHK281AMKU384485
Next Service:	109,000kms	Service History:	Yes
iagnostic testing un	only. Consideration is made	een driven up to 50km/ł	orts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comments	

Interior Comments	
Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Good
General Comments	

2WD petrol auto SUV.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Daryll Timms	
Published by:	Scott Stewart	
Inspection Date:	04 Aug 2025	

	ОК	Requires Attention	N/A
Engine	OK	Attention	IN/A
Oil level	V		
Smoke & fumes	<i>V</i>		-
Engine performance	<i>y</i>		-
Noise	<i>y</i>		
Coolant condition	<i>y</i>		
Cooling performance	\(\frac{1}{V} \)		
Radiator / Hoses (visual)	1		
Transmission			
Operation	/		Ι
Noise	/		
Clutch	-		1
CV joints	_		
Wheel bearings	1		
Brakes			
Performance	/		Ι
Hand brake	<i>J</i>		
Tyres (lowest observed tread d	enth of	l tvres)	
Left front	Cpuron		3.0 mm
Right front			3.0 mm
Left rear			3.0 mm
Right rear			3.0 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	/		
Tail lights	1		
Indicators	V V		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	1		
Window winder RL	V		
Window winder RR	1		
Rear view mirrors	V		
Radio (basic test only)	1		
CD (basic test only)			1
Number of keys	2		
Central locking	1		
Remote locking	/		
Sat. nav. (basic test only)			1
Reversing camera	1		

I have read and understood
this condition guide: