


Basic Condition Guide

| Report ID: | 27,020,505 | Version: | 3 |
|------------|-------------|----------|---|
| Created: | 21 Nov 2025 | | |

| Make: | Audi | Model: | A3 | | |
|---|-------------|------------------|-------------------|--|--|
| Body Style: | Hatchback | Year: | 2013 | | |
| Rego No.: | HDA210 | Rego Expiry: | 30 Apr 2026 | | |
| WoF Expiry: | 13 Aug 2026 | Odometer: | 104,128 Kms | | |
| Good No.: | 27020505 | VIN: | WAUZZZ8V4EA054126 | | |
| Next Service: | 114000 | Service History: | No | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | |

Key

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left rear sill damage

| Conditions During Body Inspection | Dry | |
|---|-----|--|
| Under Carriage and Under Bonnet Inspection Comments | | |

| Interior Comments | | |
|-------------------|---------|--|
| Seats: | Average | |
| Carpets: | Average | |
| Panels: | Average | |
| Dashboard: | Average | |
| General Comments | | |

Road Conditions During Test Drive Dry

Timing Chain **Engine Timing Mechanism** Evidence of Cam Belt Replacement Yes No Kms Sione Mae Inspected by: Published by: Neil Honeyman Inspection Date: 22 Aug 2025

| I have read and understoo | d |
|---------------------------|---|
| this condition guide: | |

| NAME | | | |
|------|--|--|--|

| | ОК | Requires Attention | N/A |
|--------------------------------|------------|-----------------------|----------|
| Engine | | | |
| Oil level | / | | |
| Smoke & fumes | / | | |
| Engine performance | \(\tau \) | | |
| Noise | / | | |
| Coolant condition | ~ | | |
| Cooling performance | / | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | | |
| Operation | / | | |
| Noise | / | | |
| Clutch | | | / |
| CV joints | / | | |
| Wheel bearings | / | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand brake | ~ | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | 3 | 3.0 mm |
| Right front | | 4 | 1.0 mm |
| Left rear | | 4 | 1.0 mm |
| Right rear | | 4 | 1.0 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | / | | |
| Tail lights | ~ | | |
| Indicators | V V | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | / | | |
| Window winder FL | 1 | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | / | | |
| Radio (basic test only) | 1 | | |
| CD (basic test only) | 1 | | |
| Number of keys | 1 | | |
| Central locking | 1 | | |
| Remote locking | / | | |
| Sat. nav. (basic test only) | | | / |
| Reversing camera | 1 | | |
| | | | |

| SIGNATURE | | | |
|-----------|--|--|--|