

•	Report ID:	27,035,244	Version:	4
	Created:	15 Nov 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission	,	•	
Operation	~		
Noise	/		
Clutch			~
CV joints	/		
Wheel bearings	/		
Brakes		,	
Performance	V		
Hand brake	V		
Tyres (lowest observed tread	depth of	tyres)	
Left front			8 mi
Right front			8 mi
Left rear		4	4.0 m
Right rear		4	1.0 m
Spare	Yes		
Suspension	•		
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater	_		
Operation	/		
Electrical / Accessories	•	•	
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)	V		
Reversing camera	/		

Make:	Mazda	Model:	Mazda6
Body Style:	Wagon	Year:	2016
Rego No.:	JWN727	Rego Expiry:	08 Mar 2026
WoF Expiry:	29 Sep 2026	Odometer:	139,900 Kms
Good No.:	27035244	VIN:	JM0GJ103200240408
Next Service:	143700	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends full mechanical inspection prior to purchase and this can be arranged for an additional charge.

rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Freshly serviced.

2 new tyres.

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Average	
Dashboard:	Good	
General Comments		

Fresh VTNZ warrant of fitness.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	My Auto Shop.	
Published by:	Erin White	
Inspection Date:	02 Sep 2025	

I have read and understood
this condition guide:

NAME			