

Basic Condition Guide

Report ID:	27,068,207	Version:	3
Created:	18 Dec 2025		

				Createu.		
Make:	Holden	Model:	Captiva 7			
Body Style:	SUV	Year:	2016	Engine		
Rego No.:	RHW718	Rego Expiry:	02 Jan 2026	Oil level		
WoF Expiry:	11 Sep 2026	Odometer:	130,354 Kms	Smoke & fur		
Good No.:	27068207	VIN:	KL3CD2659GB507433	Engine perfe		
Next Service:	130320km	Service History:	No	Noise		
Note: This report is	•			Coolant con		
This report is a guide diagnostic testing un	Cooling per					
·	ection prior to purchase an	d this can be arranged	Tror an additional charge.	Radiator / H		
(ey S = Scratch R	= Rust	Crack *=Dec	cals W = Significant scuffs	Transmissio		
	T = Paint defect P = P		one Chips	Operation		
0.00 W	0.11/	00 W	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Noise		
S SC W	<u>sw</u>	SC W SC W	S W S D SC W	Clutch		
			SW	CV joints		
	Ma UF		3	Wheel beari		
s sc w				Brakes		
	19 II.			Performanc		
			SDW	Hand brake		
s sc w	TR VIII	<i></i>		Tyres (lowe:		
				Left front		
			SW	Right front		
				Left rear		
s sc w	S W S	sc w sc w	S W S W	Right rear		
ote: some defects	and blemishes may not be	e displayed in the diag	ıram	Spare		
Body Inspecti	ion Comments			Suspension		
Rear Seats Re	moved - 5-Seater Onl	у		Suspension		
				Steering per		
				Shock absor		
Conditions Du	ring Body Inspection		Dry	Air Condition		
Under Carria	ge and Under Bonnet	Inspection Com	ments	Operation		
				Electrical /		
				Head lights		
				Tail lights		
Interior Comr	nents			Indicators		
Seats:	Average			Dashboard		
Carpets:	Average			Wipers (fror		
Panels:	Poor			Window wir		
Dashboard:	Average			Window wir		
General Com	ments			Window wir		
				Window wir		
				Radio (basic		
Road Conditio	CD (basic te					
Engine Timing	Mechanism	Timing Chain		Number of k		
Evidence of Ca	ım Belt Replacement	Yes	No Kms	Central lock		
Inspected by:	MAS - Gavin and	Jack		Remote lock		

		Requires	
Engino	OK	Attention	N/A
Engine Oil level	/		1
Smoke & fumes	V		
Engine performance	·/		
Noise			
Coolant condition	V		
	~		
Cooling performance Radiator / Hoses (visual)	· /		
Transmission			
Operation	J	<u> </u>	l
Noise	<i>J</i>		
Clutch	<i>J</i>		
CV joints	\(\sigma \)		
Wheel bearings	<i>J</i>		
Brakes			
Performance	J		
Hand brake	<i>y</i>		
Tyres (lowest observed tread d	enth of	tvres)	
Left front	cpair of		6.0 mm
Right front			4.0 mm
Left rear			5.0 mm
Right rear			6.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories		<u> </u>	
Head lights	/		
Tail lights	V		
Indicators	/		
Dashboard warning lights	V		
Wipers (front & rear)	1		
Window winder FL	/		
Window winder FR			
Window winder RL	✓ ✓		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			~
Number of keys	1	•	
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera	V		

I have read and understood this condition guide:

Inspection Date: 25 Sep 2025

Published by:

NAME

Francois Kleyn

SIC

SIGNATURE