

•	Report ID: 27,068,555		Version:	2
	Created:	05 Dec 2025		

Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

1

1

1

1

1

1

1 1

2

1

1

Operation

Head lights Tail lights

Indicators

N/A

8.0 mm 8.0 mm 8.0 mm 8.0 mm

AT		Pasi	c Condition Guide	Report ID:	27,068,555	Ve	ersion:	2
	nue	S Dasi	C Condition Guide	Created:	05 Dec 2025			
							Requ	iros
Make:	Volkswagen	Model:	Tiguan			ОК	Atten	
Body Style:	SUV	Year:	2014	Engine				
Rego No.:	HQR900	Rego Expiry:	17 Sep 2025	Oil level		1		\Box
WoF Expiry:	06 Oct 2026	Odometer:	133,799 Kms	Smoke & fu	mes	1		
Good No.:	27068555	VIN:	WVGZZZ5NZFW002899	Engine per	formance	1		\neg
Next Service:	143,800	Service History:	No	Noise		1		
Note: This report is	•			Coolant co	ndition	/		\neg
diagnostic testing ur	e only. Consideration is mad- ndertaken. The vehicle has b ection prior to purchase an	een driven up to 50km/l	arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge	Cooling pe	rformance	~		
				Radiator / H	loses (visual)	1		
Key $S = Scratch$ R	= Rust C = C	Crack *= Deca	ls W = Significant scuffs	Transmissi	on		•	
	T = Paint defect P = P	in dent SC = Stor	•	Operation		~		
		S		Noise		1		
				Clutch				
				CV joints		1		
	MA UT			Wheel bear	ings	1	Ì	
s sc w				Brakes			•	
	MC 11.			Performand	ce	1		
			SC	Hand brake		~		
SC					Tyres (lowest observed tread depth of tyres)			
			Left front				8	
			(Q)	Right front				8.
	\angle			Left rear				8
<u>s</u>		sc	SS	Right rear				8.
Note: some defects	and blemishes may not be	displayed in the diagra	ım	Spare		Yes		
Body Inspecti	ion Comments			Suspensio	n			
Sunroof fabric	piece worn			Suspension	performance	~		
				Steering pe	erformance	~		
				Shock abso	rbers	~		
								-

Conditions During Body Inspection	Dry

Under Carriage and Under Bonnet Inspection Comments

Interior Comments		
Seats: Average		
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

Road Condition	s During Test Drive	Dry
Engine Timing Mechanism		Timing Chain
Evidence of Can	n Belt Replacement	Yes No Kms
Inspected by:	Gary Adams	
Published by: Anna Zandstra		
Inspection Date: 17 Sep 2025		

I have read and understood		
this condition guide:	NAME	SIGNATURE