

•	Report ID:	27,090,282	Version:	3
	Created:	28 Nov 2025		

N/A

6.0 mm 7.0 mm 7.0 mm 7.0 mm

		Poci	c Condition Guide	Report ID:	27,090,282	ve	rsion:	3
	ntuet	<u> </u>		Created:	28 Nov 2025			
Make:	KIA	Model:	Sportage			ОК	Requi	
Body Style:	SUV	Year:	2017	Engine		OI.	Atten	tion
Rego No.:	KMM403	Rego Expiry:	24 Sep 2026	Oil level		V	<u> </u>	
WoF Expiry:	16 Oct 2026	Odometer:	139,223 Kms	Smoke & fu	ımes	1		-
Good No.:	27090282	VIN:	KNAPN81AMH7246007	Engine performance		-	$\dashv$	
Next Service:	149000	Service History:	Yes	Noise			$\dashv$	
lote: This report is	•			Coolant co	ndition	1		
liagnostic testing u		een driven up to 50km/l	orts have not been dismantled or of from cold. The Vendor recommends a		erformance	1		
·		u tilis cari be arrangeu i	or arradultional charge.	Radiator / I	Hoses (visual)	1		
<b>(ey</b> S = Scratch R	R = Rust C = C	rack *= Deca	s W = Significant scuffs	Transmiss	ion			
	PT = Paint defect P =		3	Operation		1		$\Box$
				Noise		~		
		S D S		Clutch				
			SW	CV joints		/		
	THE WIT			Wheel bea	rings	1		
S SC				Brakes				
				Performan	ce	1		
				Hand brak	e	~		
sc				Tyres (low	est observed tread c	lepth of	tyres)	
				Left front				6
			SC	Right front	:			7
	-			Left rear				7
		<u>s</u> s	SC	Right rear				7
Note: some defects and blemishes may not be displayed in the diagram				Spare Yes				
<b>Body Inspect</b>	ion Comments			Suspensio	on			
Windscreen has stone chips.				Suspension	n performance	/		
				Steering p	erformance	<b>'</b>		
				Shock abso	orbers	/		
Conditions During Body Inspection Dry			Air Condit	ioning / Heater				
Under Carriage and Under Bonnet Inspection Comments				Operation		/		
Runs on 91 oc	ctane fuel. Vehicle has	belly pan.		Electrical	/ Accessories			
				Head light	s	/		
				Tail lights		/		

Interior Comn	Interior Comments			
Seats: left rear seat leather damaged				
Carpets:	Carpets: Average			
Panels:	Average			
Dashboard: Average				
General Comments				

Air conditioning and heating systems good temperature along with reversing camera and sat nav working at time of inspection.

Road Condition	s During Test Drive	Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Finlay Lemmens	
Published by:	Anna Zandstra	
Inspection Date:	29 Sep 2025	

I have read and understood
this condition guide:

NAME			

SIGNATURE		

1 1

1

1 V

1

2

1

1

Indicators

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR Window winder RL

Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera