

•	Report ID: 27,091,231		Version:	2
	Created:	08 Dec 2025		

	11000	Report ID: 27,091	,231 Ve	rsion: 2				
	nue	<u> </u>	c Condition Guide	Created: 08 Dec	2025			
Make:	Holden	Model:	Barina		OK	Requires		
		2016	- Engine		Attention	N/A		
Rego No.: JUR877 Rego Expiry:		30 Nov 2025	Oil level					
WoF Expiry:	08 May 2026	Odometer:	61,712 Kms	Smoke & fumes				
Good No.:	27091231	VIN:	KL3TA48E9GB649209 Engine performance		-	· /		
Next Service:				Noise	· /	•		
Note: This report is	not a warranty			Coolant condition				
This report is a guide diagnostic testing ur	only. Consideration is made ndertaken. The vehicle has b	e for age and mileage. Pa een driven up to 50km/h	arts have not been dismantled or a from cold. The Vendor recommends a	Cooling performance		· /		
full mechanical insp	ection prior to purchase and	d this can be arranged for	or an additional charge.	Radiator / Hoses (vis		•		
Key				Transmission	uai)	<u> </u>		
	= Rust C = C		· • • • • • • • • • • • • • • • • • • •			<u> </u>	l	
D = Dent P	T = Paint defect P = Pi	in dent SC = Stor	ne Cnips	Operation	<i>'</i>			
SD	S	PW D	PW PW	Noise	•			
				Clutch		-	/	
			S	CV joints	<i>,</i>			
SD				Wheel bearings	<i>'</i>			
M	18			Brakes				
1		11 —		Performance	•	-	<u> </u>	
				Hand brake	•			
SC W				Tyres (lowest observed tread depth of tyres)				
		+	PW	Left front		6.0 mm		
				Right front			6.0 mm	
				Left rear		6.0 mn		
PW	<u>s</u>	P D	PW	Right rear		6.0 mm		
Note: some defects	and blemishes may not be	displayed in the diagra	m	Spare	Yes			
Body Inspecti	on Comments			Suspension				
•		dents and cracked	. LF tyre sidewall damage.	Suspension perform	iance 🗸			
Dashboard scra	atches.			Steering performan	ce 🗸			
				Shock absorbers	✓			
Conditions Du	ring Body Inspection	Air Conditioning / Heater						
Under Carriag	je and Under Bonnet	Operation	· ·					
Front bumper lo	ower moulding damage	ed.		Electrical / Accesso	ries			
				Head lights	· ·			
				Tail lights	· ·			
Interior Comn	nents	Indicators	· ·					
Seats: Good				Dashboard warning	lights 🗸			
Carpets: Good			Wipers (front & rear)	•				
Panels: Good			Window winder FL	•				
Dashboard: Good			Window winder FR					
			·			+		

Interior Comments			
Seats:	Good		
Carpets:	Good		
Panels:	Good		
Dashboard:	Good		
General Comments			

FWD.

Road Condition	s During Test Drive	Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Sharnae Smith			
Published by:	Darryl Kereti			
Inspection Date:	29 Sep 2025			

SIGNATURE		

1

1

1

V

2

1

•

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

Sat. nav. (basic test only) Reversing camera

CD (basic test only)

Number of keys

Central locking Remote locking

I have read and understood this condition guide:

N	Δ	M	E