

Basic Condition Guida

•	Report ID:	27,101,863	Version:	3	
	Created:	12 Nov 2025			

Make	Mozda	Model	Mozdo?				Requires	
Make:	Mazda Hatchback	Model:	Mazda3 2016	OK		OK	Attention	N/A
Body Style:		Year:	11 Mar 2026	Engine				
Rego No.:	PTG839	Rego Expiry:		Oil level		/		
WoF Expiry:	20 Oct 2026	Odometer:	178,637 Kms JM0BN543810114104	Smoke & fu	umes	/		
Good No.:	27101863	VIN: Service History:		Engine performance		'		
Next Service:	188,200	Noise		/				
	is not a warranty de only. Consideration is ma	ade for age and mileage	. Parts have not been dismantled or n/h from cold. The Vendor recommends a	Coolant co	ondition	/		
agnostic testing III mechanical ins	undertaken. The vehicle ha pection prior to purchase a	been driven up to 50kn nd this can be arranged	n/h from cold. The Vendor recommends a for an additional charge.	Cooling pe	erformance	/		
ey			1	Radiator /	Hoses (visual)	/		
-	R = Rust $C = 0$	Crack *= Dec	als W = Significant scuffs	Transmiss	ion			
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips			Operation		'			
S SC		S SC S SC	SSC	Noise		/		
				Clutch				~
	(M)-		SSC	CV joints		/		
S SC	MA W	 		Wheel bea	rings	/		
550				Brakes				
	UMF II			Performan	ice	/		
				Hand brak	e	/		
s sc				Tyres (lowest observed tread depth of tyres)				
	AR OF THE PROPERTY OF THE PROP			Left front			5	5.5 m
			S SC	Right front	t		5	5.5 m
				Left rear		6.0 mm		
s sc	W :	S SC S SC	W S SC	Right rear		6.0 mm		
ote: some defect	s and blemishes may not b	e displayed in the diag	ram	Spare		Yes		
Body Inspect	tion Comments			Suspension	on			
				Suspensio	n performance	'		
				Steering p	erformance	/		
				Shock abso	orbers	/		
Conditions Du	uring Body Inspection		Dry	Air Condit	tioning / Heater			
Under Carria	ge and Under Bonne	t Inspection Com	ments	Operation		/		
wd				Electrical	/ Accessories			
				Head light	S	/		
				Tail lights		V		
Interior Com	ments			Indicators		V		
Seats:	Average			Dashboard	d warning lights	~		
Carpets:	Average	ge			ont & rear)	'		
Panels:	anels: Average			Window w	rinder FL	V		
Dashboard: Average General Comments					rinder FR	V		
					rinder RL	/		
				Window w	vinder RR	•		
				Rear view	mirrors	~		
				Radio (bas	ic test only)	/		
Road Conditions During Test Drive Dry				CD (basic t	est only)	1		
		T: : OI :						

The second			d. ·		
I have read a	and u	nderstood	this	condition	quide:

Uriah Pepene

Abby Birch

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 02 Oct 2025

No

Timing Chain

Yes

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms

2

1

1