

Report ID:	27,103,937	Version:	2
Created:	11 Nov 2025		

E C	urne	<b>S</b> Bas	ic Condition Guide	Created: 1		
Make:	Toyota	Model:	C-HR			
Body Style:	Hatchback	Year:	2018			
Rego No.:	- I atomout	Rego Expiry:		Engine		
WoF Expiry:	03 Nov 2026	Odometer:	87,175 Kms	Oil level		
Good No.:	27103937	VIN:	7AT0H663X25144703	Smoke & fum		
Next Service:		Service History:	No	Engine perfo		
	is not a warranty	service mistory.	1.10	. Noise		
his report is a gui	de only. Consideration is m		. Parts have not been dismantled or	Coolant cond		
	undertaken. The vehicle has spection prior to purchase a		n/h from cold. The Vendor recommends a for an additional charge.	Cooling perfo		
(ey	,		,	Radiator / Ho		
•	R = Rust C =	Crack *= Dec	als W = Significant scuffs	Transmission		
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips						
		S		Noise		
-		3		Clutch		
			P	CV joints		
	NO VI			Wheel bearin		
—— <i>E</i>				Brakes		
	1195 11			Performance		
				Hand brake		
	HR 1			Tyres (lowest		
	JB N			Left front		
			(Q)	Right front		
				Left rear		
	Right rear					
lata: sama dafas:	ts and blemishes may not I	as displayed in the diag	ram.	Spare		
	tion Comments	be displayed in the diagi		Suspension		
				Suspension p		
				Steering perf		
				Shock absorb		
Conditions D	uring Body Inspection		Dry	Air Condition		
	age and Under Bonne		-	Operation		
Officer Carrie	ige and onder bonne	et inspection com	nens	Electrical / A		
•						
				Head lights		
1				Tail lights		
Interior Com				Indicators		
Seats:	Good			Dashboard w		
Carpets:	Good			Wipers (front		
Panels:	Good			Window wind		
Dashboard:	Good			Window wind		
General Con	nments			Window wind		
				Window wind		
				Rear view mi		
				Radio (basic t		
Road Conditi	ons During Test Drive	Dry		CD (basic tes		

Timing Chain

No

Yes

		Requires	
	OK	Attention	N/A
Engine			
Oil level	<b>✓</b>		
Smoke & fumes	<b>/</b>		
Engine performance	<b>/</b>		
Noise	\( \sqrt{\sq}}}}}}}\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}\sqrt{\sqrt{\sqrt{\sq}}}}}}}}\signt{\sqrt{\sqrt{\sq}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}		
Coolant condition	<b>/</b>		
Cooling performance	<b>/</b>		
Radiator / Hoses (visual)	<b>/</b>		
Transmission			
Operation	•		
Noise	•		
Clutch			<b>V</b>
CV joints	<b>/</b>		
Wheel bearings	<b>/</b>		
Brakes			
Performance	<b>'</b>		
Hand brake	/		
Tyres (lowest observed tread de	pth of	tyres)	
Left front		7	7.0 mm
Right front		7	7.0 mm
Left rear		8	3.0 mm
Right rear		8	3.0 mm
Spare	No		
Suspension			
Suspension performance	V		
Steering performance	<b>/</b>		
Shock absorbers	<b>V</b>		
Air Conditioning / Heater			
Operation		<u> </u>	
Electrical / Accessories	-		
Head lights	<u> </u>		
Tail lights	<u> </u>		
Indicators	✓ ✓		
	1		
Dashboard warning lights Winers (front & rear)	·		
Wipers (front & rear) Window winder FL	·		
Window winder FL Window winder FR	· ·		
	· ·		
Window winder RL			
Window winder RR	<b>/</b>		
Rear view mirrors	<b>V</b>		
Radio (basic test only)	<b>V</b>		
CD (basic test only)	·		
Number of keys	2	1	
Central locking	/		
Pomoto locking	<b>/</b>		
Remote locking		1	
Sat. nav. (basic test only)			<b>/</b>

I have read and understood this condition guide:

Chris Buckley

Charlotte Jane

10 Nov 2025

Engine Timing Mechanism

Inspected by:

Published by:

Inspection Date:

Evidence of Cam Belt Replacement

NAME

SIGNATURE

Kms