

Report ID:	27,103,985	Version:	1
Created:	07 Nov 2025		

Requires Attention

N/A

	Turners Basic Condition Guide		Report ID:	27,103,985	Ve	
	orner	S Basi	c Condition Guide	Created:	07 Nov 2025	
Make:	Toyota	Model:	C-HR			
	Hatchback	Year:	2017			OK
Body Style:	Пакспраск		2017	Engine		
Rego No.:	05 Nov. 0000	Rego Expiry:	05.040.16	Oil level		<b>/</b>
WoF Expiry:	05 Nov 2026	Odometer:	95,848 Kms	Smoke & fu	ımes	~
Good No.:	27103985	VIN:	7AT0H663X25006799	Engine per	formance	/
Next Service:	105,846 Kms	Service History:	No	Noise		<b>/</b>
<b>Note: This report i</b> This report is a guid	•	de for age and mileage. I	Parts have not been dismantled or	Coolant co	ndition	<b>/</b>
diagnostic testing ι		oeen driven up to 50km/	h from cold. The Vendor recommends a	Cooling pe	rformance	V
Key	, , , , , , , , , , , , , , , , , , , ,			Radiator / H	Hoses (visual)	~
-	R = Rust	Crack *= Deca	ls W = Significant scuffs	Transmiss	ion	
D = Dent F	PT = Paint defect P = P	in dent SC = Stor		Operation		~
				Noise		1
				Clutch		
				CV joints		1
	TO ST			Wheel bea	rings	1
SPTW				Brakes		
	1197 11			Performan	ce	V
				Hand brake	2	1
	HR W			Tyres (lowe	est observed tread o	depth of
				Left front		
			(Q)	Right front		
				Left rear		
D				Right rear		
Note: some defect:	s and blemishes may not be	e displayed in the diagra	ım	Spare		Yes
	ion Comments			Suspensio	n	
				Suspension	n performance	V
				-	erformance	1
				Shock abso		1
Conditions During Body Inspection Dry					Air Conditioning / Heater	
	ge and Under Bonnet	: Inspection Comm	•	Operation		V
				Electrical /	Accessories	
				Head lights	5	1
				Tail lights		1
Interior Com	ments			Indicators		1
Seats:	Stains on front lef	t seat			warning lights	1
Carpets:	Good			Wipers (fro		1
Panels:	Good			Window w		1
Dashboard:	Good			Window w		1
Sasrisoura.				TTITIOUV VV		<b>—</b>

NOISE		
Coolant condition	V	
Cooling performance	V	
Radiator / Hoses (visual)	V	
Transmission		
Operation	V	
Noise	V	
Clutch		<b>V</b>
CV joints	V	
Wheel bearings	V	
Brakes		
Performance	V	
Hand brake	V	
Tyres (lowest observed tread	depth of tyres)	)
Left front		6.9 mm
Right front		6.8 mm
Left rear		6.9 mm
Right rear		6.9 mm
Spare	Yes	
Suspension	_	
Suspension performance	V	
Steering performance	V	
Shock absorbers	V	
Air Conditioning / Heater	,	
Operation	V	
Electrical / Accessories		
Head lights	V	
Tail lights	V	
Indicators	V V	
Dashboard warning lights	V	
Wipers (front & rear)	V	
Window winder FL	V	
Window winder FR	V	
Window winder RL	V	
Window winder RR	1	
Rear view mirrors	1	
Radio (basic test only)	V	
CD (basic test only)		· /
Number of keys	2	
Central locking	V	
Remote locking	V	
Sat. nav. (basic test only)		<b>/</b>

I have read and understood this condition guide:

Hoani Saunders

Robert Chardon 07 Nov 2025

**General Comments** 

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Engine Timing Mechanism

Inspected by:

Published by:

Inspection Date:

Dry

Timing Chain

Yes

NAME

No

SIGNATURE

Kms