


Make:	Mitsubishi	Model:	Triton
Body Style:	Utility	Year:	2022
Rego No.:	PCD363	Rego Expiry:	28 Dec 2025
WoF Expiry:	12 Mar 2026	Odometer:	86,579 Kms
Good No.:	27105638	VIN:	MMAJLKL10NH017064
Next Service:	90000	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comments	
4x4	

Interior Comments	
Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Uriah Pepene		
Published by:	Ajaykumar Muruganandam		
Inspection Date:	14 Oct 2025		

I have read and understood
this condition guide:

NAME _____

SIGNATURE