

•	Report ID:	27,106,541	Version:	3
	Created:	13 Nov 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	1		
Engine performance	1		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			<u> </u>
Operation	V		
Noise	1		
Clutch			1
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	·		
Hand brake	1		
Tyres (lowest observed tread	depth of	tyres)	l
Left front	T T		5.0 mm
Right front		·	5.0 mm
Left rear		-	7.0 mm
Right rear			3.0 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater		•	
Operation	'		
Electrical / Accessories			
Head lights	V		
Tail lights	V		
Indicators	V		
Dashboard warning lights	V		
Wipers (front & rear)	V		
Window winder FL	~		
Window winder FR	1		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	/		
CD (basic test only)	'		
Number of keys	2		
Central locking	1		
Remote locking	1		
Sat. nav. (basic test only)			/
Reversing camera	/		


Make:	Nissan	Model:	Tiida
Body Style:	Sedan	Year:	2007
Rego No.:	RJR355	Rego Expiry:	24 Mar 2026
WoF Expiry:	25 Nov 2026	Odometer:	107,170 Kms
Good No.:	27106541	VIN:	7AT0DH78X16107819
Next Service:	117,120 km	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Windscreen slight pitting.

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Front wheel drive.

Interior Comments		
Seats:	Good	
Carpets:	Average	
Panels:	Average	
Dashboard:	Good	
General Comments		

Freshly serviced.

Fresh VTNZ warrant of fitness.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Imraan Bryant	
Published by:	Erin White	
Inspection Date:	18 Oct 2025	

have read and understood
his condition quide

NAME			