

Report ID:	27,117,950	Version:	2
Created:	30 Oct 2025		

OK

1

Requires Attention

N/A

		Basic Condition Guide			Report ID:	27,117,950	
	nue	S Basi	c Condition (Juide	Created: 30 Oct 20		
			1				
Make:	Toyota	Model:	Markx				
Body Style:	Sedan	Year:	2010		Engine		
Rego No.:	NQP449	Rego Expiry:	12 Nov 2025		Oil level		
WoF Expiry:	04 Oct 2026	Odometer:	187,711 Kms		Smoke & fumes		
Good No.:	27117950	VIN:	7AT0H64TX210	10286	Engine performance		
Next Service:	197000	Service History:	No		Noise		
Note: This report is	•				Coolant co	ndition	
diagnostic testing ur	only. Consideration is mad ndertaken. The vehicle ha b	een driven up to 50km/	h from cold. The Vendor	nantled or recommends a	Cooling pe	rformance	
	ection prior to purchase and	d this can be arranged fo	or an additional charge.			Hoses (visual)	
Key S = Scratch R :	= Rust	rack * = Decal	ls W – Sign	nificant scuffs	Transmissi		
	$\Gamma = \text{Paint defect} \Gamma = \text{Pi}$		3	illicarit scurs	Operation		
					Noise		
	W	PTP		SP	Clutch		
				D.DT.C.	CV joints		
				DPTC	Wheel bearings		
SPTC	SPTC					Brakes	
	M 11				Performan	ce	
				PT SC	Hand brake	2	
R SC	18			3	Tyres (lowe	est observed trea	
					Left front		
			(Q)	D	Right front		
					Left rear		
sc		<u>s</u> (s) (w	S SC	Right rear		
Note: some defects a	and blemishes may not be	displayed in the diagra	m		Spare		
Body Inspection	on Comments				Suspensio	n	
					Suspension	performance	
					Steering pe	erformance	
					Shock abso	rbers	
Conditions Dur	ing Body Inspection		Dry		Air Condit	ioning / Heater	
Under Carriag	e and Under Bonnet	Inspection Comm	ents		Operation		
RWD					Electrical /	Accessories	
					Head lights		
					Tail lights		
Interior Comm	Interior Comments				Indicators		
	1_						

Engine performance	'		
Noise	'		
Coolant condition	V		
Cooling performance	'		
Radiator / Hoses (visual)	'		
Transmission			
Operation	~		
Noise	/		
Clutch			/
CV joints			/
Wheel bearings	'		
Brakes			
Performance	~		
Hand brake	'		
Tyres (lowest observed tread	depth of ty	yres)	
Left front		5	.5 mm
Right front		6	.5 mm
Left rear		6	.0 mm
Right rear		7	.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	'		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	'		
Electrical / Accessories			
Head lights	~		
Tail lights	'		
Indicators	'		
Dashboard warning lights	'		
Wipers (front & rear)	V V		
Window winder FL			
Window winder FR	V V		
Window winder RL			-
Window winder RR	~		
Rear view mirrors	'		
Radio (basic test only)	~		
CD (basic test only)			/
Number of keys	1		
Central locking	/		
Remote locking	'		
Sat. nav. (basic test only)			✓

Road Condition	s During Test Drive	Dry		
Engine Timing Mechanism		Unknown		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Arunachalam Sub	ramanian		
Published by:	Isaiah Talauta			
Inspection Date:	12 Oct 2025			

I have read and	understood	this	condition	auid
I Have I cad alla	unacistooa	uiiio	Condition	quiu

Poor

Good Good

Good

Seats:

Carpets:

Panels: Dashboard:

General Comments

Reversing camera