

Basic Condition Guide

| Report ID: | 27,118,080 | Version: | 1 |
|------------|-------------|----------|---|
| Created: | 11 Nov 2025 | | |

2

1

1

Number of keys

Central locking
Remote locking

Sat. nav. (basic test only)
Reversing camera

| U | ntue | S Bas | sic Condition Guide | Created: 11 Nov 2025 | | | |
|----------------------|---|---|---------------------------|---|---------------------------------------|-----------|----------|
| Make: | Ssangyong | Model: | Korando | | 011 | Requires | |
| Body Style: | SUV | Year: | 2015 | Engine | OK | Attention | N/A |
| Rego No.: | KSQ571 | Rego Expiry: | 17 Oct 2026 | Oil level | V | | |
| WoF Expiry: | 25 Jul 2026 | Odometer: | 97,644 Kms | Smoke & fumes | 1 | | |
| Good No.: | 27118080 | VIN: | KPTB0B18SEP187831 | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Next Service: | 106000 | Service History: | No | Engine performance | 1 | | |
| Note: This report i | s not a warranty | 1 | Noise Coolant condition | 1 | | | |
| his report is a guic | de only. Consideration is m undertaken. The vehicle ha | ade for age and mileage a been driven up to 50kn | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | |
| ull mechanical insp | oection prior to purchase a | and this can be arranged | for an additional charge. | Cooling performance Radiator / Hoses (visual) | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | - |
| Key | | | | | | | |
| | | Crack *= Dec | | Transmission | | | |
| D = Dent F | PT = Paint defect P = | Pin dent SC = St | one Chips | Operation | V | | |
| SSC | W | SC S SC | W | Noise | - | | - |
| | | | | Clutch | | | |
| | \sim (0) | | S SC | CV joints | / | | - |
| S SC _ | | | | Wheel bearings | / | | |
| | | | HIV | Brakes | | Ī | |
| | | | SC | Performance | V | | |
| | | | | Hand brake | / | | |
| s sc | | | | Tyres (lowest observed tread depth of tyres) Left front 7.4 mm | | | |
| | | | | Left front | | | |
| | | | Right front | 7.2 mm | | | |
| S | W | s sc sc | WSC | Left rear | 4.9 mm | | |
| | | | | Right rear | 5.4 mm | | |
| | s and blemishes may not l | be displayed in the diag | ram | Spare | Yes | | |
| | ion Comments | | | Suspension | | l | |
| Minor stonechi | ips front windscreen | | | Suspension performance | - | | |
| | | | | Steering performance | / | | <u> </u> |
| | | | 1- | Shock absorbers | / | | |
| | ıring Body Inspection | | Dry | Air Conditioning / Heater | | Ī | |
| | ge and Under Bonne | et Inspection Com | ments | Operation | / | | |
| All wheel drive | | | | Electrical / Accessories | | | |
| | | | | Head lights | V | | |
| | | | | Tail lights | / | | |
| Interior Com | _ | | | Indicators | / | | |
| Seats: | Good | | | Dashboard warning lights | / | | |
| Carpets: | Good | | | Wipers (front & rear) | / | | |
| Panels: | | | | Window winder FL | ~ | ļ | |
| Dashboard: | Good | | Window winder FR | ~ | | | |
| General Com | ments | | Window winder RL | ~ | | | |
| | | | | Window winder RR | ~ | | |
| | | | | Rear view mirrors | ' | | |
| | | | | Radio (basic test only) | / | | |
| Road Condition | ons During Test Drive | Dry | | CD (basic test only) | | | 1 |
| | | 1 | | | | | |

| Engine Timing N | Engine Timing Mechanism | | | |
|------------------|-------------------------|--------|----|-----|
| Evidence of Can | n Belt Replacement | Yes | No | Kms |
| Inspected by: | Cameron Senior-A | Arnold | | |
| Published by: | Janine Bell | | | |
| Inspection Date: | 10 Oct 2025 | | | |

I have read and understood this condition guide: