

Basic Condition Guide

•	Report ID:	27,120,666	Version:	1
	Created:	28 Nov 2025		

		OK	Requires Attention	N/A
	Engine	OK _	Attention	13/73
	Oil level	V		
	Smoke & fumes	1		
367	Engine performance	1		
	Noise	1	-	
	Coolant condition	1		
or mends a	Cooling performance	1		
	Radiator / Hoses (visual)	1		
	Transmission			
nt scuffs	Operation	V	l	
	Noise	1		
	Clutch	+		
	CV joints	V		
S	Wheel bearings	1		
	Brakes			
	Performance	V	<u> </u>	<u> </u>
	Hand brake	1		
			turos)	
	Tyres (lowest observed tread Left front	<u>аеритог</u>		1.8 mm
				5.0 mm
	Right front Left rear			1.9 mm
				1.8 mm
	Right rear	N/A		+.0 11111
	Spare Suspension	IN/A		
		V	<u> </u>	
	Suspension performance	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
	Steering performance Shock absorbers	V		
			l	
	Air Conditioning / Heater	V		
	Operation		l	
	Electrical / Accessories		l	<u> </u>
	Head lights	1		
	Tail lights	-		
	Indicators	1		
	Dashboard warning lights	V		
	Wipers (front & rear)			
	Window winder FL Window winder FR	1	-	
	Window winder FR Window winder RL	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	-	
			-	
	Window winder RR	1	-	
	Rear view mirrors	V	-	
	Radio (basic test only)	<i>V</i>		
	CD (basic test only)	2	<u> </u>	
	Number of keys	2	1	I
Kms	Central locking	<i>V</i>		
	Remote locking	/		
	Sat. nav. (basic test only)			-
	Reversing camera			

Make:	Nissan	Model:	Serena
Body Style:	Wagon	Year:	2015
Rego No.:	vvagori	Rego Expiry:	2010
WoF Expiry:	21 Nov 2026	Odometer:	74,331 Kms
Good No.:	27120666	VIN:	7AT0DH3FX25120867
Next Service:	84,400 Kms	Service History:	No
diagnostic testing ur	only. Consideration is made	een driven up to 50km/l	arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.
•	= Rust C = C	rack *= Deca	ls W = Significant scuff
D = Dent P	$\Gamma = Paint defect P = Pi$	in dent SC = Sto	_
SC O			S
	and blemishes may not be on Comments	displayed in the diagra	im .
Body Inspecti	on Comments	displayed in the diagra	Dry
Body Inspecti	· · · · · · · · · · · · · · · · · · ·		Dry
Conditions Dui Under Carriag	ring Body Inspection le and Under Bonnet		Dry
Conditions Dur Under Carriag 2WD	ring Body Inspection le and Under Bonnet	Inspection Comm	Dry
Conditions Dur Under Carriag 2WD Interior Comn Seats:	ring Body Inspection le and Under Bonnet ments Wear on drivers s	Inspection Comm	Dry
Conditions Dur Under Carriag 2WD Interior Comn Seats: Carpets:	ring Body Inspection le and Under Bonnet Wear on drivers s Stains on front floor	Inspection Comm	Dry
Conditions Dur Under Carriag 2WD Interior Comm Seats: Carpets: Panels:	ring Body Inspection le and Under Bonnet Wear on drivers s Stains on front flor	Inspection Comm	Dry
Conditions Dur Under Carriag 2WD Interior Comm Seats: Carpets: Panels: Dashboard:	ring Body Inspection le and Under Bonnet Wear on drivers s Stains on front flor Good Good	Inspection Comm	Dry
Conditions Dur Under Carriag 2WD Interior Comm Seats: Carpets: Panels:	ring Body Inspection le and Under Bonnet Wear on drivers s Stains on front flor Good Good	Inspection Comm	Dry
Conditions Dur Under Carriag 2WD Interior Comm Seats: Carpets: Panels: Dashboard:	ring Body Inspection le and Under Bonnet Wear on drivers s Stains on front flor Good Good Good ments	Inspection Comme	Dry
Conditions Dur Under Carriag 2WD Interior Comm Seats: Carpets: Panels: Dashboard:	ring Body Inspection le and Under Bonnet Wear on drivers s Stains on front flood Good Good ments During Test Drive	Inspection Comm	Dry

Hoani Saunders

NAME

Ryan Stanley

Inspection Date: 26 Nov 2025

I have read and understood this condition guide:

Inspected by:
Published by: