

## **Basic Condition Guide**

| • | Report ID: | 27,124,833  | Version: | 4 |
|---|------------|-------------|----------|---|
|   | Created:   | 27 Nov 2025 |          |   |

N/A

7.0 mm 7.0 mm 6.0 mm

| Make:                                 | Tesla  | Model:                    | Model 3                   |                              | ОК                                    | Requires<br>Attention |  |
|---------------------------------------|--|---------------------------|---------------------------|------------------------------|---------------------------------------|-----------------------|--|
| Body Style:                           | Sedan  | Year:                     | 2021                      | Engine                       | OK                                    | Attention             |  |
| Rego No.:                             | NPT749   | Rego Expiry:              | 06 Jan 2026               | Oil level                    |                                       | <u> </u>              |  |
| WoF Expiry:                           | 13 Aug 2026  | Odometer:                 | 107,808 Kms               | Smoke & fumes                |                                       |                       |  |
| Good No.:                             | 27124833   | VIN:                      | LRW3F7FA3MC241198         | Engine performance           |                                       |                       |  |
| Next Service:                         | 105887 kms   | Service History:          | No                        | Noise                        |                                       |                       |  |
| Note: This report is r                | not a warranty   | Coolant condition         | 1                         |                              |                                       |                       |  |
| diagnostic testing und                | only. Consideration is made<br>dertaken. The vehicle has b | een driven up to 50km/ł   | Cooling performance       | 1                            |                                       |                       |  |
| ull mechanical inspe                  | ction prior to purchase an                                 | Radiator / Hoses (visual) | 1                         |                              |                                       |                       |  |
| (ey                                   | Durat C. C   | Transmission              |                           |                              |                                       |                       |  |
|                                       | = Rust C = C<br>= Paint defect P = Pi                      |                           | Operation                 | T                            | <u> </u>                              |                       |  |
|                                       | Tunit defect   |                           | Noise                     |                              |                                       |                       |  |
|                                       | W  | S                         | Clutch                    |                              |                                       |                       |  |
|                                       |  |                           | CV joints                 | · /                          | -                                     |                       |  |
|                                       | $(0)_{\mathbb{Z}}$   |                           |                           | Wheel bearings               | 1                                     |                       |  |
| $\Box$ $\Box$                         |  |                           |                           | Brakes                       |                                       |                       |  |
| $\overline{}$                         | D.   |                           | All                       | Performance                  | V                                     |                       |  |
| $\mathcal{M}$                         |  |                           |                           | Hand brake                   | +                                     |                       |  |
|                                       |  |                           |                           | Tyres (lowest observed tread | donth of                              | turos                 |  |
|                                       |  | $\longrightarrow$         |                           | Left front                   | ved tread deptit of tyres/            |                       |  |
|                                       |  |                           | D                         |                              |                                       |                       |  |
|                                       |  |                           |                           | Right front<br>Left rear     |                                       |                       |  |
|                                       | W  |                           | $\mathbf{w}$              |                              |                                       |                       |  |
|                                       |  |                           |                           | Right rear                   | N/A                                   |                       |  |
|                                       | and blemishes may not be                                   | displayed in the diagra   | m                         | Spare                        | IN/A                                  |                       |  |
| Body Inspection                       | on comments  |                           |                           | Suspension performance       | V                                     |                       |  |
|                                       |  |                           |                           | Suspension performance       | V                                     | -                     |  |
|                                       |  |                           |                           | Steering performance         | 1                                     |                       |  |
| Canaditiana Duni                      | : Ddl  |                           | Dry                       | Shock absorbers              |                                       |                       |  |
|                                       | ing Body Inspection  | luana atian Caman         | Air Conditioning / Heater | · ·                          | l                                     |                       |  |
| Left front tyre sic                   | e and Under Bonnet   | inspection Comm           | Operation                 |                              |                                       |                       |  |
| Len non tyre sic                      | de wall damage.  |                           |                           | Electrical / Accessories     |                                       | <u> </u>              |  |
|                                       |  |                           |                           | Head lights                  | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |                       |  |
| 1                                     |  |                           |                           | Tail lights                  |                                       |                       |  |
| Interior Comm                         | 1  |                           | Indicators                | V                            |                                       |                       |  |
| Seats:                                | Good   |                           |                           | Dashboard warning lights     | <b>/</b>                              | -                     |  |
| Carpets:                              | Good   |                           |                           | Wipers (front & rear)        | V                                     | -                     |  |
| Panels:                               |  |                           |                           | Window winder FL             | V                                     |                       |  |
| Dashboard:                            | Good   |                           | Window winder FR          | <b>/</b>                     |                                       |                       |  |
| General Comm                          |  |                           |                           | Window winder RL             | <i>'</i>                              |                       |  |
| windscreen stor<br>plastic cover torr | ne chip, tail gate strut<br>າ.                             | broken, L rear refle      | Window winder RR          | /                            |                                       |                       |  |
| ,                                     |  |                           |                           | Rear view mirrors            | <i>\</i>                              |                       |  |
|                                       |  | I_                        |                           | Radio (basic test only)      | /                                     |                       |  |
|                                       | s During Test Drive  | Dry                       | CD (basic test only)      | <u> </u>                     | <u> </u>                              |                       |  |
| Engine Timing I                       |  | Unknown                   | Number of keys            | 2                            | 1                                     |                       |  |
|                                       | m Belt Replacement   | Yes                       | Central locking           | /                            | <u> </u>                              |                       |  |
| Inspected by:                         | Marlon Espena  |                           |                           | Remote locking               |                                       | 1                     |  |

I have read and understood this condition guide:

Inspection Date: 20 Oct 2025

Published by:

NAME \_\_

Henry Manders

SIGNATURE

Sat. nav. (basic test only)

Reversing camera