


Basic Condition Guide

Report ID:	27,127,863	Version:	1
Created:	03 Nov 2025		

Make:	Holden	Model:	Captiva 7	
Body Style:	suv	Year:	2018	
Rego No.:	LQG684	Rego Expiry:	23 Sep 2026	
WoF Expiry:	17 Nov 2026	Odometer:	110,069 Kms	
Good No.:	27127863	VIN:	KL3CA26U9JB028367	
Next Service:	120,000	Service History:	No	
Note: This report is not a warranty				
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				

Key S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips

W = Significant scuffs * = Decals



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Sunroof doesn't operate

Conditions During Body Inspection Dry **Under Carriage and Under Bonnet Inspection Comments**

Interior Comments	
Seats:	Average
Carpets:	Poor
Panels:	Average
Dashboard:	Average

General Comments

Drivers seat does not slide Back/Forward

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Unknown		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Tyler Le Bherz			
Published by: Tyler Le Bherz				
Inspection Date:	03 Nov 2025			

	OK	Requires Attention	N/A
Engine		7100011011	
Oil level	V		
Smoke & fumes	V		
Engine performance	/		
Noise	V		
Coolant condition			
Cooling performance	V		
Radiator / Hoses (visual)	/		
Transmission			
Operation	V		
Noise	/		
Clutch			1
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	V		
Hand brake	V		
Tyres (lowest observed tread d	epth of	tvres)	
Left front			3.5 mm
Right front			3.5 mm
Left rear			1.5 mm
Right rear			5.5 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	V		
Shock absorbers	V		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	V		
Tail lights	/		
Indicators			
Dashboard warning lights	V		
Wipers (front & rear)	/		
Window winder FL			
	1	l	
Window winder FR	V		
Window winder FR Window winder RL	V V		
	/		
Window winder RL	V		
Window winder RL Window winder RR Rear view mirrors	V V		
Window winder RL Window winder RR Rear view mirrors Radio (basic test only)	V V V		
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	V V V		<i>'</i>
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	\(\frac{1}{\cute{V}} \)		~
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	\(\times \)		V
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking Remote locking	\(\frac{1}{\cute{V}} \)		V
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	\(\frac{1}{\cute{V}} \)		<i>V</i>

I have read and understood this condition guide:

NAME

SIGNATURE