

•	Report ID:	27,127,925	Version:	1
	Created:	26 Nov 2025		

Basic Condition Guide			Report ID:	27,127,925	Ve	rsion: 1		
	Jillei			Created:	26 Nov 2025			
Make:	Jaguar	Model:	XF			Requires	NI/A	
Body Style: Sedan Year: 2013		2013	Engine		OK	Attention	N/A	
Rego No.:			26 Mar 2026	Oil level		V		
WoF Expiry:	21 Aug 2026	Odometer:	125,363 Kms	Smoke & fumes		-		
Good No.:	27127925	VIN:	SAJKC05M7DPS93566			1		
Next Service:	Next Service: 132900 Service History: No Engine performance Noise			Torridite	· ·			
Note: This report is	not a warranty	•		Coolant condition		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
diagnostic testing un	dertaken. The vehicle has be	een driven up to 50km/ł	arts have not been dismantled or n from cold. The Vendor recommends a	Cooling pe		1		
full mechanical inspe	ection prior to purchase and	d this can be arranged fo	or an additional charge.		Hoses (visual)	1		
Key				Transmissi				
	= Rust $C = C$ C = C $C = Paint defect C = C$			Operation		V		
	- rume defect 1 - 11	mucht 5e-5tol	The emps	Noise		1		
	W	W	W	Clutch				
				CV joints		1		
	$(0)_{\mathbb{F}}$		(\bigcirc)	Wheel bear	rinas	1		
W				Brakes				
MACHINE					ce	V		
				Hand brake		1		
	R			Tyres (lowest observed tread depth of tyres)				
\mathcal{L}				Left front		5.0 mm		
						5.0 mi		5.0 mm
				Left rear		6.0 mn		
	W	S	W	Right rear		6.0 mn		
Note: some defects	and blemishes may not be	displayed in the diagra	ım	Spare		Yes		
Body Inspection				Suspensio	n			
				Suspension	n performance	1		
				Steering pe	erformance		V	
				Shock abso	orbers	~		
Conditions During Body Inspection Dry					Air Conditioning / Heater			
Under Carriage and Under Bonnet Inspection Comments				Operation		V		
				Electrical /	Accessories			
				Head lights	5	/		
				Tail lights		V		
Interior Comments				Indicators		/		
Seats: Average			Dashboard	warning lights		V		
Carpets: Average			Wipers (fro	nt & rear)	V			
Panels: hood lining loose			Window wi	inder FL	V			
Dashboard: Average			Window wi	inder FR	1			

Interior Comments				
Seats:	Average			
Carpets:	Average			
Panels:	hood lining loose			
Dashboard:	Average			
General Comments				

Steering shimmy

Engine light on

Road Condition	s During Test Drive	Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Greg Morgan	
Published by:	Francois Kleyn	
Inspection Date:	22 Nov 2025	

have read and understood
this condition guide:

NAME			

SIGNATURE			

1

1

•

1

1

1

Window winder RL

Window winder RR

Radio (basic test only) CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Rear view mirrors

Number of keys

Central locking Remote locking