

Basic Condition Guide


Report ID:	27,130,822	Version:	3
Created:	06 Nov 2025		

MG	Model:	3	
Hatchback	Year:	2024	
Rego No.: QNL996		29 Apr 2025	
30 Apr 2027	Odometer:	939 Kms	
Good No.: 27130822		LSJZ14U97RS041245	
10,000km	Service History:	Yes	
	Hatchback QNL996 30 Apr 2027 27130822	Hatchback Year: QNL996 Rego Expiry: 30 Apr 2027 Odometer: 27130822 VIN:	

Note:	This	renort	is n	ot a	warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

ney				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments				
Seats:	Good			
Carpets:	Good			
Panels:	Good			
Dashboard:	Good			

General Comments

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Chain		
Evidence of Cam Belt Replacement		Yes No Kms		
Inspected by:	Kereti Kereti			
Published by:	Kereti Kereti			
Inspection Date:	06 Nov 2025			

	ОК	Requires Attention		
Engine	<u> </u>	Accention		,,,,
Oil level	/			
Smoke & fumes	/			
Engine performance				
Noise	V V			
Coolant condition	/			
Cooling performance	/			
Radiator / Hoses (visual)	/			
Transmission				
Operation	/			
Noise	/			
Clutch				√
CV joints	/			
Wheel bearings	/			
Brakes				
Performance	/			
Hand brake	✓			
Tyres (lowest observed tread d	epth of	tyres)		
Left front			6	mm
Right front			6	mm
Left rear			2	mm
Right rear			6	mm
Spare	Yes			
Suspension				
Suspension performance				
Steering performance				
Shock absorbers				
Air Conditioning / Heater				
Operation				
Electrical / Accessories		Γ		
Head lights				
Tail lights	/		_	
Indicators	V		_	
Dashboard warning lights				
Wipers (front & rear)	/			
Window winder FL	<u> </u>			
Window winder FR				
Window winder RL				
Window winder RR	/			
Rear view mirrors	<u>/</u>			
Radio (basic test only)				
CD (basic test only)	2		<u> </u>	_
Number of keys	∠ ✓		1	
Central locking				
Remote locking Sat. nav. (basic test only)	V			
Reversing camera			\vdash	
neversing camera				

I have read and understood this condition guide:

NAME