

Basic Condition Guide

•	Report ID:	27,133,574	Version:	2
	Created:	31 Oct 2025		


Make:	Mazda	Model:	Mazda3
Body Style:	Hatchback	Year:	2009
Rego No.:	EZK112	Rego Expiry:	18 Nov 2025
WoF Expiry:	11 Jul 2026	Odometer:	115,384 Kms
Good No.:	27133574	VIN:	JM0BL10L100107443
Next Service:	125,400 km	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

itcy				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

1 parcel tray retainer pin missing. Tow eye cover taped on.

Conditions During Body Inspection	Dry		
Under Carriage and Under Ronnet Inspection Comments			

Interior Comments Seats: Average Carpets: Average Panels: Average Dashboard: Average

General Comments

Air conditioning and heating systems ok. Remote controls function but have to push buttons hard

Road Conditions During Test Drive		Dry
Engine Timing I	Mechanism	Timing Chain
Evidence of Can	n Belt Replacement	Yes No Kms
Inspected by:	Gary Adams	
Published by:	Anna Zandstra	
Inspection Date:	22 Oct 2025	

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	\(\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\tinx{\ti}\xitit\}\\ \text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texitit}\xititt{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\tinit}\\ \tittt{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi}\tint{\text{\text{\tinit}}\\ \tittt{\text{\text{\text{\text{\text{\text{\text{\ti}\tittit{\text{\text{\texi}\tittitt{\text{\text{\text{\texi}\tittit{\text{\til\titt{\text{\text{\texi}\tittit{\text{\ti}\tittitt{\tiint{\tex{\tiin}\tittit{\text{\tii}\tittit{\text{\texi}\tii}\tittit{\text{\titil\tittit{\tiint{\tiint{\tiint{\tii}\tiint{\tii}\tiin		
Radiator / Hoses (visual)	/		
Transmission		l	
Operation	V		
Noise	/		
Clutch			~
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake			
Tyres (lowest observed tread d	epth of	tyres)	
Left front			6.0 mm
Right front			6.0 mm
Left rear			1.0 mm
Right rear			5.0 mm
Spare	Yes		
Suspension			
Suspension performance			
Steering performance	· ·		
Shock absorbers			
Air Conditioning / Heater			
Operation			
Electrical / Accessories	•		
Head lights	V		
Tail lights	~		
Indicators			
Dashboard warning lights	✓		
Wipers (front & rear)	·		
Window winder FL	~		
Window winder FR	·		
Window winder RL			
Window winder RR			
Rear view mirrors			
Radio (basic test only)	~		
CD (basic test only)			
Number of keys	2	<u> </u>	L
· · · · · · · · · · · · · · · · · · ·			
Central locking	4		
Remote locking			
Sat. nav. (basic test only)			<u> </u>
Reversing camera			

I have read and understood this condition guide: