

•	Report ID: 27,134,106		Version:	3
	Created:	17 Nov 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	V		
Engine performance	V		
Noise	/		
Coolant condition	V		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	1		
Noise	/		
Clutch			·
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	V	Ι	
Hand brake	<i>J</i>		
Tyres (lowest observed tread d	enth of	turos)	
Left front	еритог		3.0 mm
Right front			
Left rear			
Right rear	Voc		3.0 mm
Spare	Yes		
Suspension		T T	
Suspension performance	- 1		
Steering performance	•		
Shock absorbers	•		
Air Conditioning / Heater		T	T
Operation	/		
Electrical / Accessories		T	ı
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		<u> </u>
Wipers (front & rear)	/		<u> </u>
Window winder FL	/		
Window winder FR	•		<u> </u>
Window winder RL			_
Window winder RR			_
Rear view mirrors	/		<u></u>
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			/

Make:	Nissan	Model:	NV200
Body Style:	Van	Year:	2017
Rego No.:	PWG726	Rego Expiry:	27 Sep 2026
WoF Expiry:	03 Jul 2026	Odometer:	164,584 Kms
Good No.:	27134106	VIN:	7AT0DH8MX23026383
Next Service:	171,000 km	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Front wheel drive.

Interior Comments		
Seats:	Average	
Carpets:	Good	
Panels:	Poor	
Dashboard:	Good	
General Comments		

Brand new stereo head unit installed.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
3 3		
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Imraan Bryant	
Published by:	Erin White	
Inspection Date:	21 Oct 2025	

have read and understood
this condition quide

NAME			