

Report ID:	27,134,958	Version:	1	
Created:	06 Nov 2025			

N/A

7.5 mm 7.5 mm 5.5 mm 6.5 mm

	urner	C Basi	c Condition Guide	Report ID:	27,134,956	ve	ersion:	1
	Offici			Created:	06 Nov 2025			
Make:	Honda	Model:	Civic			OV	Requ	ires
Body Style:	Hatchback	Year:	2010	Engine		OK	Atten	tion
Rego No.:	HKP659	Rego Expiry:	04 Sep 2026			V		
WoF Expiry:	20 Nov 2026	Odometer:	128,089 Kms	Oil level Smoke & fumes		1		
Good No.:	27134958	VIN:	SHHFK1750AU004439			1	\vdash	-
Next Service:	135026	Service History:	No	Engine performance Noise			+	
lote: This report	is not a warranty		Coolant condition		1	_		
diagnostic testing	de only. Consideration is mad undertaken. The vehicle ha b	oeen driven up to 50km,	Cooling performance		1	\vdash	-	
ull mechanical ins	pection prior to purchase an	d this can be arranged f	or an additional charge.	Radiator / Hoses (visual)		1	 	
Key				Transmission				
	R = Rust $C = CPT = Paint defect$ $P = P$			Operation	1011	· /		
) – DCIII			nic Criips	Noise		1	+	-
s sc	W	s sc s sc	S SC	Clutch		1		
				CV joints		1	+	
	(0)		S SC	Wheel bear	rings	1	†	
S SC				Brakes				
	119 11		Performan	ce	V			
			S SC	Hand brake		1	†	
S SC	HR			Tyres (lowest observed tread depth of tyres)				
				Left front				7
			S SC	Right front		7		
				Left rear		5		
s sc		ssc ssc		Right rear				6
lote: some defect	s and blemishes may not be	e displayed in the diagra	am	Spare		Yes		
Body Inspec	tion Comments			Suspensio	n			
Minor stone ch	nips on windscreen			Suspension	n performance	~		
				Steering pe	erformance	~		
				Shock abso	orbers	~		
Conditions D	uring Body Inspection		Dry	Air Condit	ioning / Heater			
Under Carria	ge and Under Bonnet	Inspection Comm	nents	Operation		/		
Front wheel dr	rive		Electrical /	Accessories				
			Head lights	5	/			
				Tail lights		V		
Interior Com	ments			Indicators		/		
Seats:	Good			Dashboard	warning lights	/		
Carpets:	Good			Wipers (fro	nt & rear)	/		
Panels:	Good			Window w	inder FL	/		
Dashboard:	Good			Window w	inder FR	~		
General Com	nments			Window w	inder RL	/		
				Window w	inder RR	/		
				Rear view r	mirrors	/		
							1	Т

I have read and	l understood this	condition guide

Janine Bell

18 Oct 2025

Cameron Senior-Arnold

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Engine Timing Mechanism

Inspected by:

Published by:

Inspection Date:

Dry

Timing Chain

Yes

No

Radio (basic test only)

2

1

1

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms