

Basic Condition Guide

•	Report ID: 27,137,556		Version:	3
	Created:	02 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	~		
Engine performance	/		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	1		
Noise	1		
Clutch			1
CV joints	1		
Wheel bearings	1		
Brakes			<u> </u>
Performance	V		
Hand brake	1		
Tyres (lowest observed tread	donth of	turos)	
Left front	церитог		6.0 mm
Right front			3.0 mm
Left rear			4.0 mm
Right rear			4.0 mm
Spare	Yes		
Suspension		Ī	l e
Suspension performance	V		
Steering performance	/		
Shock absorbers			
Air Conditioning / Heater			ı
Operation	/		
Electrical / Accessories		1	
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	V		
Window winder FL			
Window winder FR	/		
Window winder RL	/		
Window winder RR	~		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)	1		
Number of keys	2	•	
Central locking	1		
Remote locking		·	
Sat. nav. (basic test only)		 	-
Reversing camera	1		<u> </u>
	•	ı	


Make:	KIA	Model:	Sorento
Body Style:	SUV	Year:	2012
Rego No.:	GQL970	Rego Expiry:	09 Dec 2025
WoF Expiry:	19 Dec 2025	Odometer:	114,966 Kms
Good No.:	27137556	VIN:	KNAKU814SD5370391
Next Service:	125,000 kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = ScratchR = RustC = Crack* = DecalsW = Significant scuffs D = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments

And

Seats:	Good
Carpets:	Good
Panels:	Door trim scratches
Dashboard:	scratches

General Comments

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Vasanthakumar Mayilswamy		
Published by:	Clive Joseph		
Inspection Date:	20 Nov 2025		

I have read and understood this condition guide:

NAME			

SIGNATURE