

Report ID:	27,139,267	Version:	1
Created:	03 Nov 2025		

AT.		Dooi	a Canalitian Cuida	Report ID:	27,139,267	Ve	rsion: 1	
	urner	S Basi	c Condition Guide	Created:	03 Nov 2025		·	
							Requires	
Make:	Mazda	Model:	Roadster			OK	Attention	N/A
Body Style:	Convertible	Year:	2006	Engine				
Rego No.:	KNE103	Rego Expiry:	04 Nov 2025	Oil level	Oil level			
WoF Expiry:	26 Sep 2026	Odometer:	100,544 Kms	Smoke & fumes		/		
Good No.:	27139267	VIN:	7AT0C12YX17100984	Engine performance		1		
Next Service:	110500	Service History:	No	_ Noise		1		
Note: This report is	•	d - f - v - v d :	Danka harra wakibaasa disamankia di an	Coolant co	ndition	1		
diagnostic testing ur	ndertaken. The vehicle ha b	been driven up to 50km/	Parts have not been dismantled or 'h from cold. The Vendor recommends a	Cooling pe	rformance	1		
full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Hoses (visual)	1		
Key S = Scratch R	= Rust	irack * = Deca	ls W = Significant scuffs	Transmiss	ion			
	$\Gamma = \text{Paint defect} P = P$		•	Operation		V		
				Noise		1		
S		sc	S	Clutch				1
				CV joints				1
			S	Wheel bea	rings	1		
S				Brakes				
	19 11			Performan	ce	V		
] -		Hand brake		1		
s	D			Tyres (lowest observed tread depth of tyres)				
- Q				Left front		4.5 mm		
			(Q)	Right front		4.5 mm		
				Left rear				2.5 mm
P	S		SS	Right rear				2.5 mm
Note: some defects	and blemishes may not be	displayed in the diagra	ım.	Spare		No		
Body Inspecti		. displayed in the diagre		Suspensio	n			
, ,				•	n performance	V		
				•	erformance	1		
				Shock abso		1		
Conditions Dur	ring Body Inspection		Dry		ioning / Heater			
	e and Under Bonnet	Inspection Comm	•	Operation				
		•		•	'Accessories			
				Head lights	5	V		
				Tail lights		1		
Interior Comm	nents			Indicators		1		
Seats:	Poor				warning lights	1		
Carpets:	Good		<u> </u>	Wipers (fro		1		
Panels:				Window w		1		
Dashbaard:	Good		·	Windoww				

Interior Comm	Comments	
Seats:	Poor	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
General Comn	nents	

Air Con Not Getting Cold

Road Condition	s During Test Drive	Dry
Engine Timing Mechanism		Timing Chain
Evidence of Can	n Belt Replacement	Yes No Kms
Inspected by:	Kris Milne	
Published by:	Sara Haggerty	
Inspection Date:	03 Nov 2025	

Right rear			2.5 m
Spare	No		
Suspension			
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		/	
Electrical / Accessories			
Head lights	V		
Tail lights	V		
Indicators	V		
Dashboard warning lights	V		
Wipers (front & rear)	V		
Window winder FL	'		
Window winder FR	V		
Window winder RL			/
Window winder RR			/
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	V		
Number of keys	2		
Central locking	V		
Remote locking	V		
Sat. nav. (basic test only)			~
Reversing camera			1

I have read and understood this condition guide:

NAME